

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority					Photo Reference		Date	Identification			Exterior Materials	Map No.	I.D. No.	
Street Number and Name		H	S	M	S	L	Roll	Frame		Slide	Property Type	Subtype				Stylistic Influence
900	N. Azalea Dr.					X				1950	Domestic Single			Wood	93B	810
901	N. Azalea Dr.			X						1950	Domestic Single			Stone	93B	809
904	N. Azalea Dr.			X						1950	Domestic Single			Red Brick	93B	811
907	N. Azalea Dr.			X						1950	Domestic Single			Wood	93B	808
910	N. Azalea Dr.					X				1950	Domestic Single			Wood	93B	812
913	N. Azalea Dr.					X				1950	Domestic Single			Wood	93B	807
918	N. Azalea Dr.					X				1955	Domestic Single			Synthetic Siding	93B	813
919	N. Azalea Dr.			X						1950	Domestic Single			Wood	93B	806
922	N. Azalea Dr.			X						1950	Domestic Single		Ranch	Wood	93B	814
925	N. Azalea Dr.			X						1950	Domestic Single		Colonial Revival	Synthetic Siding	93B	805
1002	N. Azalea Dr.			X						1950	Domestic Single		Ranch	Stone	93B	815
1003	N. Azalea Dr.			X						1950	Domestic Single			Yellow Brick	93B	804A
1003	N. Azalea Dr. (rear)					X				1950	Domestic Auxiliary	Garage Apartment			93B	804B
2311	S. Bateman Ave.	X					07	25		1930	Domestic Single		Tudor Revival	Stone	97	1338
2321	S. Bateman Ave.					X				1930	Domestic Single			Stone	97	1337
2403	S. Bateman Ave.			X						1940	Domestic Single		Minimal	Brick	97	1336
2407	S. Bateman Ave.			X						1940	Domestic Single		Tudor Revival	Brick/Vinyl Siding	97	1335
2413	S. Bateman Ave.			X						1940	Domestic Single		Classical Revival	Brick	97	1334
2419	S. Bateman Ave.					X				1940	Domestic Single		Colonial Revival	Brick	97	1333
2503	S. Bateman Ave.			X						1945	Domestic Single			Red Brick	97	1332
2509	S. Bateman Ave.			X						1940	Domestic Single			Brick	97	1331
1923	S. Beckham Rd.	X					05	19		1890	Domestic Single	L Plan	Queen Anne	Wood	99	1129
2000	S. Beckham Rd.			X						1940	Domestic Single		Tudor Revival	Yellow Brick	99	1122
2011	S. Beckham Rd.			X						1950	Domestic Single		Colonial Revival	Pink Brick	99	1123
107	S. Belmead Ln.	X					07	10		1950	Domestic Single		Colonial Revival	Brick	122	1254
119	S. Belmead Ln.	X					07	09		1955	Domestic Single		Colonial Revival	Brick	122	1253
201	S. Belmead Ln.	X					07	08		1950	Domestic Single		Colonial Revival	Yellow Brick	122	1380
211	S. Belmead Ln.	X					07	07		1950	Domestic Single		Colonial Revival	Red Brick	122	1252
219	S. Belmead Ln.	X					06	35 07 :06		1950	Domestic Single		Colonial Revival	Pink Brick	122	1251
224	S. Belmead Ln.			X						1950	Domestic Single		Colonial Revival	Red Brick	122	1255
225	S. Belmead Ln.	X					07	05		1950	Domestic Single		Colonial Revival	Red Brick	122	1250
1116	S. Belmont Ave.			X						1940	Domestic Single		Colonial Revival	Red Brick	80	390

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority		Photo Reference		Date	Identification		Stylistic Influence		Exterior Materials		Map No.	I.D. No.
Street Number and Name	HISM	M	SL	Roll	:Frame Slide		Property Type	Subtype						
1124 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Yellow Brick		80	391	
1200 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Brick		80	392	
1206 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Red Brick		80	393	
1212 S. Belmont Ave.		X				1950	Domestic Single		Colonial Revival	Brick		80	394	
1215 S. Belmont Ave.		X				1940	Domestic Single		Tudor Revival	Brick		80	389	
1218 S. Belmont Ave.		X				1940	Domestic Single		Minimal	Brick		80	395	
1300 blk. S. Belmont Ave.		X				1940	Infrastructure and Utilities	Bridge		Stone		80	260	
1300 blk. S. Belmont Ave.		X				1950	Infrastructure and Utilities	Drainage Channel		Concrete		80	271	
1300 blk. S. Belmont Ave.		X				1950	Domestic Single		Ranch	Brick		80	397	
1306 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Brick		80	396	
1309 S. Belmont Ave.		X				1940	Domestic Single			Brick		80	388	
1319 S. Belmont Ave.		X			03:02	1940	Domestic Single		Colonial Revival	Yellow Brick		80	387	
1320 S. Belmont Ave.		X				1950	Domestic Single		Colonial Revival	Brick		80	398	
1330 S. Belmont Ave.		X				1950	Domestic Single			Brick		80	399	
1401 S. Belmont Ave.		X			03:01	1950	Domestic Single		Colonial	Mixed Brick		80	386	
1402 S. Belmont Ave.		X				1950	Domestic Single			Brick/Wood		80	400	
1413 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Red Brick/Wood		80	385	
1414 S. Belmont Ave.			X			1940	Domestic Single		Colonial	Stone		80	401	
1421 S. Belmont Ave.		X				1940	Domestic Single			Yellow Brick		80	384	
1500 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Brick		80	402	
1506 S. Belmont Ave.		X				1945	Domestic Single		Colonial Revival	Brick		80	403	
1602 S. Belmont Ave.		X				1950	Domestic Single		Colonial Revival	Wood		80	404	
1608 S. Belmont Ave.		X				1950	Domestic Single			Asbestos		80	405	
1609 S. Belmont Ave.		X				1940	Domestic Single		Colonial Revival	Wood		80	383	
1700 blk. S. Belmont Ave.		X				1950	Domestic Single			Brick		83A	447	
1709 S. Belmont Ave.		X				1950	Domestic Multiple	Duplex		Wood		83A	423	
1713 S. Belmont Ave.		X				1950	Domestic Single			Red Brick		83A	446	
1718 S. Belmont Ave.		X				1950	Domestic Single			Asbestos		83A	448	
1719 S. Belmont Ave.			X			1950	Domestic Single			Brick		83A	445	
1720 S. Belmont Ave.		X				1945	Domestic Single			Wood		83A	449	
1723 S. Belmont Ave.			X			1950	Domestic Single			Red Brick/Synthetic		83A	444	
1724 S. Belmont Ave.		X				1955	Domestic Single			Wood		83A	450	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Sheet Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	M	S				L	Roll				
1727	S. Belmont Ave.	X					Domestic Single				Wood	83A	443
1804	S. Belmont Ave.				X		Domestic Single				Aluminum	83A	451
1805	S. Belmont Ave.	X					Domestic Single				Yellow Brick	83A	442
1809	S. Belmont Ave.	X					Domestic Single				Red Brick	83A	441
1810	S. Belmont Ave.				X		Domestic Single				Synthetic Siding	83A	452
1818	S. Belmont Ave.	X					Domestic Single				Brick	98	1037
1823	S. Belmont Ave.				X		Domestic Single				Brick	98	1067
1900	S. Belmont Ave.	X					Domestic Single				Yellow Brick	98	1038
1900 blk.	S. Belmont Ave.	X					Domestic Single				Brick	98	1041
1900 blk.	S. Belmont Ave.	X					Domestic Single	Cross Gabled Bungalow			Yellow Brick	98	1042
1900 blk.	S. Belmont Ave.				X		Domestic Single				Asbestos	98	1065
1901	S. Belmont Ave.	X					Domestic Single				Red Brick	98	1066
1910	S. Belmont Ave.	X					Domestic Single				Red Brick	98	1039
1911-09	S. Belmont Ave.	X					Domestic Multiple	Duplex			Yellow Brick	98	1064
1919	S. Belmont Ave.				X		Domestic Single				Red Brick	98	1063
1926	S. Belmont Ave.	X					Domestic Single				Brick	98	1040
1927	S. Belmont Ave.	X					Domestic Single				Red Brick	98	1062
2001	S. Belmont Ave.	X					Domestic Single				Yellow Brick	98	1061
2007	S. Belmont Ave.	X					Domestic Single				Brick	98	1060
2014	S. Belmont Ave.	X					Domestic Single	Cross Gabled Bungalow			Brick	98	1043
2015	S. Belmont Ave.	X					Domestic Single				Yellow Brick	98	1059
2020	S. Belmont Ave.	X					Domestic Single	Cross Gabled Bungalow			Red Brick	98	1044
2021	S. Belmont Ave.	X					Domestic Single				Red Brick	98	1058
2023	S. Belmont Ave.	X					Domestic Single				Brick	98	1057
2024	S. Belmont Ave.	X					Domestic Single	Cross Gabled Bungalow			Yellow Brick	98	1045A
2024	S. Belmont Ave. (rear)				X		Domestic Auxiliary	Garage Apartment			Wood	98	1045B
2027	S. Belmont Ave.	X					Domestic Single				Brick	98	1056
2028	S. Belmont Ave.				X		Domestic Single				Brick	98	1046
2103	S. Belmont Ave.	X					Domestic Single				Brick	98	1055
2106	S. Belmont Ave.				X		Domestic Single				Wood	98	1047
2107	S. Belmont Ave.	X					Domestic Single				Yellow Brick	98	1054
2110	S. Belmont Ave.	X					Domestic Single				Wood	98	1048

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype					
2113	S. Belmont Ave.		X			1935	Domestic Single		Tudor Revival	Brick	98	1053	
2116	S. Belmont Ave.		X			1940	Domestic Single		Tudor Revival	Brick	98	1049	
2117	S. Belmont Ave.		X			1935	Domestic Single		Tudor Revival	Yellow Brick	98	1052	
2120	S. Belmont Ave.			X		1955	Domestic Single		Ranch	Pink Brick	98	1050	
2121	S. Belmont Ave.		X			1940	Domestic Single			Brick	98	1051A	
2121	S. Belmont Ave. (rear)		X			1940	Domestic Auxiliary	Garage Apartment		Wood	98	1051B	
402	S. Bluebonnet Dr.		X		06 : 23	1950	Domestic Single		Colonial Revival	Brick	1058	1217	
403	S. Bluebonnet Dr.		X			1950	Domestic Single		Colonial Revival	Red Brick	1058	1218	
410	S. Bluebonnet Dr.		X			1950	Domestic Single		Colonial Revival	Mixed Brick	1058	1219	
415	S. Bluebonnet Dr.		X		06 : 07	1950	Domestic Single		Colonial Revival	Pink Brick	105A	1216	
818	S. Bois D'Arc Ave.		X			1935	Domestic Single	Side Gabled Bungalow	Colonial Revival	Red Brick	70	64	
826 -28	S. Bois D'Arc Ave.		X			1935	Domestic Multiple	Duplex	Tudor Revival	Yellow Brick	70	65A	
826 1/2	S. Bois D'Arc Ave.			X		1935	Domestic Auxiliary	Garage Apartment		Asbestos	70	65B	
832	S. Bois D'Arc Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	70	66	
836 -38	S. Bois D'Arc Ave.		X			1935	Domestic Multiple	Duplex	Tudor Revival	Red Brick	70	67A	
840	S. Bois D'Arc Ave.			X		1935	Domestic Auxiliary	Garage Apartment		T-111	70	67B	
910	S. Bois D'Arc Ave.		X			1945	Domestic Single			Asbestos	70	68	
918	S. Bois D'Arc Ave.			X		1925	Domestic Single			Wood	70	69	
922	S. Bois D'Arc Ave.		X			1945	Domestic Single		Colonial Revival	Wood	70	70A	
922	S. Bois D'Arc Ave. (rear)			X		1945	Domestic Auxiliary	Garage Apartment		Wood	70	70B	
805	S. Broadway		X		01 : 12	1915	Domestic Single		Classical Revival	Wood	70	43	
815	S. Broadway		X		01 : 11	1900	Domestic Single		Classical Revival	Wood	70	42	
900 blk.	S. Broadway		X			1935	Infrastructure and Utilities	Underpass		Concrete	70	41	
911	S. Broadway		X		01 : 10	1930	Civic	Club	Classical Revival	Red Brick/Stucco	70	40	
1000 blk.	S. Broadway		X			1935	Domestic Multiple	Apartment		Brick/Yellow Brick	70	38	
1015	S. Broadway		X			1935	Domestic Single		Tudor Revival	Yellow Brick	70	39	
1100 blk.	S. Broadway		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	169	
1100 blk.	S. Broadway		X		02 : 08	1935	Domestic Single		Tudor Revival	Stucco	79	172	
1103	S. Broadway		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	170	
1114 -16	S. Broadway		X			1935	Domestic Multiple	Duplex	Tudor Revival	Red Brick	79	171	
1123	S. Broadway		X			1935	Domestic Single		Tudor Revival	Brick	79	168	
1125	S. Broadway		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	167	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority	Photo Reference	Date	Property Type	Identification	Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H S M M S L L	Roll : frame Slide			Subtype				
1130	S. Broadway	X		1935	Domestic Single		Tudor Revival	Yellow Brick	79	173
1203	S. Broadway	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	166
1204	S. Broadway	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	174
1206	S. Broadway	X		1935	Domestic Single		Tudor Revival	Yellow Brick	79	175
1209	S. Broadway	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	165
1212	S. Broadway	X		1935	Domestic Single		Tudor Revival	Brick	79	176A
1212	S. Broadway (rear)	X		1935	Domestic Auxiliary	Garage Apartment	Tudor Revival	Wood	79	176B
1215	S. Broadway	X		1935	Domestic Single		Classical Revival	Brick	79	114A
1215	S. Broadway (rear)	X		1935	Domestic Auxiliary	Green House		Wood/Metal	79	114B
1400 blk.	S. Broadway	X	01 : 33	1935	Infrastructure and Utilities	Headwall		Stone	79	136A
1400 blk.	S. Broadway	X	01 : 34	1935	Infrastructure and Utilities	Bridge		Stone	79	136B
1400 blk.	S. Broadway	X		1935	Infrastructure and Utilities	Headwall		Stone	79	136C
1400 blk.	S. Broadway	X		1935	Recreation	Theater		Stone	79	136D
1400 blk.	S. Broadway	X	01 : 35	1935	Infrastructure and Utilities	Spillway		Stone	79	136E
1721	S. Broadway	X		1935	Commercial	1-Part Commercial Block		Brick	84	512
1801	S. Broadway	X		1935	Domestic Single	1-Part Commercial Block	Mission Revival	Concrete	84	513
1901	S. Broadway	X		1940	Commercial	1-Part Commercial Block		Stucco	95	942
608	W. Camellia St.	X		1955	Domestic Single		International	Pink Brick	96	1142
615	W. Camellia St.	X		1950	Domestic Single		Ranch	Stone	96	1146
622	W. Camellia St.	X		1950	Domestic Single		Colonial Revival	Pink Brick	96	1143
700 blk.	W. Camellia St.	X		1950	Domestic Single		Colonial Revival	Brick	96	1144
705	W. Camellia St.	X		1955	Domestic Single		Ranch	Yellow Brick	96	1145
900	W. Camellia St.	X		1955	Domestic Single		Ranch	Wood/Red Brick	93B	821
901	W. Camellia St.	X		1950	Domestic Single		Ranch	Wood	93B	820
909	W. Camellia St.	X		1940	Domestic Single			Wood	93B	819
912	W. Camellia St.	X		1950	Domestic Single			Asbestos	93B	822
915	W. Camellia St.	X		1950	Domestic Single			Stone	93B	818
918	W. Camellia St.	X		1950	Domestic Single			Yellow Brick	93B	823
1112	S. Chilton Ave.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	137
1116	S. Chilton Ave.	X		1935	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Yellow Brick	79	138
1122	S. Chilton Ave.	X		1935	Domestic Single			Brick/Asbestos	79	139
1200 blk.	S. Chilton Ave.	X	02 : 14	1935	Infrastructure and Utilities	Street		Red Brick	79	252

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Style				
1202	S. Chilton Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick/Stucco	79	140	
1212	S. Chilton Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	141	
1216	S. Chilton Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Ranch	Brick	79	142	
1220	S. Chilton Ave.		X			1935	Domestic Single		Colonial Revival	Brick	79	143	
1312	S. Chilton Ave.		X		02 : 10	1935	Domestic Single		Tudor Revival	Brick	79	144A	
1312	S. Chilton Ave. (rear)		X			1935	Domestic Auxiliary	Garage Apartment	Tudor Revival	Wood	79	144B	
1318	S. Chilton Ave.		X			1935	Domestic Single		Colonial Revival	Brick	79	145	
1404	S. Chilton Ave.	X			02 : 11	1935	Domestic Single		Tudor Revival	Yellow Brick	79	146A	
1404	S. Chilton Ave.		X			1935	Domestic Auxiliary	Garage Apartment	Tudor Revival	Yellow Brick	79	146B	
1410	S. Chilton Ave.		X		02 : 12	1935	Domestic Single		Tudor Revival	Red Brick/Asbestos	79	147	
1416	S. Chilton Ave.		X			1935	Domestic Single		Colonial Revival	Red Brick	79	148	
1506	S. Chilton Ave.	X			03 : 33	1935	Domestic Single		Classical Revival	Brick	84	531A	
1506	S. Chilton Ave. (rear)	X			04 : 01	1935	Domestic Auxiliary	Garage Apartment	Colonial Revival	Brick	84	531B	
1514	S. Chilton Ave.	X			03 : 34	1935	Domestic Single		Tudor Revival	Brick	84	532	
1516	S. Chilton Ave.	X			03 : 35	1935	Domestic Single		Colonial Revival	Brick	84	533	
1603	S. Chilton Ave.	X			04 : 10	1940	Domestic Single		Colonial Revival	Yellow Brick	85	647	
1604	S. Chilton Ave.		X			1950	Domestic Single		Colonial Revival	Brick	84	534	
1608	S. Chilton Ave.		X			1940	Domestic Single		Colonial Revival	Brick	84	535	
1609	S. Chilton Ave.		X		04 : 09	1935	Domestic Single		Tudor Revival	Red Brick	85	646A	
1609	S. Chilton Ave. (rear)		X			1940	Domestic Auxiliary	Garage Apartment		Wood	85	646B	
1615	S. Chilton Ave.	X			04 : 08	1940	Domestic Single		Colonial Revival	Brick	85	645	
1616	S. Chilton Ave.	X			03 : 16	1935	Domestic Single		Tudor Revival	Brick	84	496	
1619	S. Chilton Ave.	X			04 : 07	1935	Domestic Single		Colonial Revival	Red Brick	85	644	
1717	S. Chilton Ave.	X			04 : 06	1950	Domestic Single		Colonial Revival	Mixed Brick	85	643	
1719	S. Chilton Ave.		X			1940	Domestic Single			Stone	85	642	
1805	S. Chilton Ave.		X			1940	Domestic Single		Colonial Revival	Red Brick	85	641	
1819	S. Chilton Ave.	X			04 : 11	1940	Domestic Single		Colonial Revival	Stone	85	640	
1901	S. Chilton Ave.		X			1950	Domestic Single			Stucco/Wood	94	915	
1915	S. Chilton Ave.		X			1950	Domestic Single		Colonial Revival	Brick	94	914	
1925	S. Chilton Ave.	X			04 : 29	1950	Domestic Single		Monterey	Wood/Synthetic Sliding	94	913	
2001	S. Chilton Ave.	X			04 : 28	1950	Domestic Single		Colonial Revival	Red Brick	94	912A	
2001	S. Chilton Ave. (rear)	X				1950	Domestic Auxiliary	Garage Apartment	Colonial Revival	Red Brick	94	912B	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference		Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M	Roll	Frame			Slide	Subtype				
2023	S. Chilton Ave.	X			04 : 27		1950	Domestic Single			Colonial Revival	Pink Brick	94	911
2029	S. Chilton Ave.	X			04 : 26		1950	Domestic Single			Colonial Revival	Brick	94	910
2030	S. Chilton Ave.		X		05 : 09		1950	Commercial			Colonial Revival	Pink Brick	95	935
2212	S. Chilton Ave.		X		06 : 25		1940	Domestic Single			Colonial Revival	Pink Brick	96A	1285
2217	S. Chilton Ave.		X		05 : 24		1950	Domestic Single			Classical Revival	Brick	96	1194
2222	S. Chilton Ave.		X		06 : 26		1950	Domestic Single			Classical Revival	Red Brick/Wood	96A	1284
2223	S. Chilton Ave.		X		05 : 23		1950	Domestic Single			Colonial Revival	Pink Brick	96	1193
2229	S. Chilton Ave.		X		05 : 22		1945	Domestic Single			Ranch	Pink Brick	96	1192
2232	S. Chilton Ave.		X		06 : 27		1950	Domestic Single			Colonial Revival	Red Brick	96A	1283
2300	S. Chilton Ave.		X		06 : 28		1950	Domestic Single			Colonial	Brick	96A	1282
2307	S. Chilton Ave.		X				1950	Domestic Single				Brick	96	1191
2312?	S. Chilton Ave.		X		06 : 29		1950	Domestic Single			Classical Revival	Brick	96A	1281
2317	S. Chilton Ave.			X			1940	Domestic Single			Tudor Revival	Mixed Brick	96	1190
2318	S. Chilton Ave.		X		06 : 30		1940	Domestic Single			Monterey	Brick/Wood	96A	1280
2322	S. Chilton Ave.		X				1950	Domestic Single			Ranch	Brick	96A	1279
2323	S. Chilton Ave.			X			1955	Domestic Single			Ranch	Pink Brick	96	1189
2415	S. Chilton Ave.			X			1955	Domestic Single			Ranch	Mixed Brick	96	1188
2425	S. Chilton Ave.		X		05 : 21		1950	Domestic Single			Colonial Revival	Pink Brick	96	1187
2512	S. Chilton Ave.		X		06 : 31		1950	Domestic Single			Colonial Revival	Red Brick	96A	1278
2520	S. Chilton Ave.		X		06 : 32		1950	Domestic Single			Colonial Revival	Mixed Brick	96A	1277
2600	S. Chilton Ave.		X		05 : 25		1950	Domestic Single			Colonial Revival	Pink Brick	105	1200
2601	S. Chilton Ave.		X		06 : 03		1940	Domestic Single			Colonial Revival	Red Brick	105	1205
2609	S. Chilton Ave.		X		06 : 02		1950	Domestic Single			Colonial Revival	Mixed Brick	105	1204
2610	S. Chilton Ave.		X		05 : 26 06 : 01		1950	Domestic Single			Colonial Revival	Yellow Brick	105	1201
2623	S. Chilton Ave.			X			1925	Domestic Single				Wood	105	1203
2627	S. Chilton Ave.		X				1950	Domestic Single				Red Brick	105	1202
2700 blk.	S. Chilton Ave.		X				1950	Domestic Single			Colonial Revival	Red Brick	105B	1228
2701	S. Chilton Ave.		X				1950	Domestic Single			Ranch/Colonial	Mixed Brick	105B	1231
2706	S. Chilton Ave.			X			1955	Domestic Single			Ranch	Brick	105B	1220
2720	S. Chilton Ave.		X				1950	Domestic Single			Colonial Revival	Brick	105B	1221
2720	S. Chilton Ave.		X				1950	Domestic Single			Ranch	Red Brick	105B	1222
2723	S. Chilton Ave.		X				1955	Domestic Single			Ranch/Colonial	Red Brick	105B	1230

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Subtype				
2734	S. Chilton Ave.		X			1950	Domestic Single		Ranch	Ranch	Pink Brick	1058	1223
2736	S. Chilton Ave.			X		1955	Domestic Single			Colonial	Red Brick	1058	1224
2739	S. Chilton Ave.		X			1950	Domestic Single			Ranch/Colonial	Mixed Brick	1058	1229
2746	S. Chilton Ave.		X			1950	Domestic Single			Colonial	Pink Brick	1058	1225
2754	S. Chilton Ave.			X		1955	Domestic Single			Ranch	Mixed Brick	1058	1226
2769	S. Chilton Ave.		X		06:24	1950	Domestic Single			Colonial Revival	Red Brick	1058	1227
800 -1000blk S. College Ave.		X			01:17	1925	Infrastructure and Utilities	Street			Red Brick		72
800 blk. S. College Ave.			X			1935	Domestic Single				Red Brick	70	44
809 S. College Ave.			X			1935	Domestic Single			Tudor Revival	Brick	70	44
815 2 S. College Ave.			X			1935	Domestic Single			Tudor Revival	Yellow Brick	70	63
821 -19 S. College Ave.			X			1935	Domestic Single		Cross Gabled Bungalow	Tudor Revival	Brick	70	62
825 S. College Ave.			X			1935	Domestic Multiple		Duplex	Tudor Revival	Brick	70	61
829 S. College Ave.			X			1930	Domestic Single		Cross Gabled Bungalow	Tudor Revival	Brick	70	60
835 S. College Ave.			X			1950	Domestic Single				Wood	70	59
836 S. College Ave.			X			1935	Domestic Single		Cross Gabled Bungalow	Tudor Revival	Yellow Brick	70	58
842 S. College Ave.			X		01:14	1935	Domestic Single			Colonial Revival	Red Brick	70	45
902 S. College Ave.			X			1935	Domestic Single			Tudor Revival	Red Brick/Stucco	70	46
921 S. College Ave.			X			1925	Domestic Single			Colonial Revival	Brick	70	47
922 S. College Ave.			X		01:15	1955	Domestic Single			Colonial Revival	Red Brick	70	57
922 S. College Ave. (rear)			X			1935	Domestic Single			Tudor Revival	Stone	70	48A
1000 2 S. College Ave.			X		X	1935	Domestic Auxiliary	Garage Apartment			T-111	70	48B
1002 S. College Ave.		X				1935	Domestic Single			Tudor Revival	Brick	70	56
1005 S. College Ave.			X		01:16	1930	Domestic Single			Tudor Revival	Red Brick	70	49
1009 S. College Ave.			X			1935	Domestic Single		Cross Gabled Bungalow	Tudor Revival	Brick	70	55
1014-16 S. College Ave.			X			1910	Domestic Multiple		Duplex	Classical Revival	Synthetic Siding	70	54
1015 S. College Ave.			X			1935	Domestic Multiple		Duplex		Wood	70	50
1019 S. College Ave.			X			1925	Domestic Single		Front Gabled Bungalow	Craftsman	Wood	70	53
1019 S. College Ave. (rear)			X			1935	Domestic Single				Brick	70	52A
1023 S. College Ave.			X			1935	Domestic Auxiliary	Garage Apartment			Stucco/Wood	70	52B
1100-1400blk S. College Ave.			X		02:09	1935	Domestic Single		Street		Brick/Stucco	70	51
1103 S. College Ave.			X			1935	Infrastructure and Utilities				Red Brick	79	249
1103 S. College Ave. (rear)			X			1935	Domestic Single			Tudor Revival	Brick	79	160A
1103 S. College Ave. (rear)			X			1935	Domestic Auxiliary	Garage Apartment			Wood	79	160B

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference Roll :Frame Slide	Date	Identification			Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M			SL	Property Type	Subtype				
1105	S. College Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	159	
1106	S. College Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	161	
1110	S. College Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	162	
1111	S. College Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	158A	
1111	S. College Ave. (rear)		X			1935	Domestic Auxiliary	Garage Apartment		Wood	79	158B	
1114	S. College Ave.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	163	
1119	S. College Ave.		X			1930	Domestic Single	Side Gabled Bungalow		Wood	79	157	
1121	S. College Ave.		X			1925	Domestic Single	Front Gabled Bungalow	Craftsman	Wood	79	156	
1203	S. College Ave.		X			1935	Domestic Single			Yellow Brick	79	155	
1208	S. College Ave.		X		02 : 07	1935	Domestic Single		Spanish Colonial	Brick	79	164A	
1208	S. College Ave. (rear)		X			1935	Domestic Auxiliary	Garage Apartment		Wood	79	164B	
1211	S. College Ave.		X			1935	Domestic Single			Yellow Brick/Synthetic	79	154	
1310	S. College Ave.		X			1935	Domestic Auxiliary	Garage Apartment		Wood	79	120B	
1311-07	S. College Ave.		X			1935	Domestic Multiple	Duplex	Tudor Revival	Brick	79	153	
1315	S. College Ave.		X		02 : 06	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Stone/Stucco	79	152	
1321	S. College Ave.		X		02 : 05	1935	Domestic Single		Tudor Revival	Yellow Brick	79	151	
1401	S. College Ave.		X		02 : 03	1940	Domestic Single		Mediterranean	Yellow Brick	79	130A	
1411	S. College Ave.		X		02 : 02	1935	Domestic Single		Tudor Revival	Metal/Brick	79	150A	
1411	S. College Ave. (rear)		X			1935	Domestic Auxiliary	Garage Apartment	Tudor Revival	Metal/Brick	79	150B	
1421	S. College Ave.		X		02 : 01	1935	Domestic Single		Tudor Revival	Yellow Brick	79	149	
1500 1600blk.	S. College Ave.		X		03 : 32	1935	Infrastructure and Utilities	Street		Red Brick	84	536	
1503	S. College Ave.		X		03 : 31	1935	Domestic Single		Mediterranean	Yellow Brick	84	522A	
1503	S. College Ave. (rear)		X			1935	Domestic Auxiliary	Garage Apartment	Mediterranean	Yellow Brick	84	522B	
1509	S. College Ave.		X		03 : 30	1935	Domestic Single		Tudor Revival	Brick	84	521A	
1509	S. College Ave. (rear)		X			1960	Domestic Auxiliary	Garage Apartment		Wood	84	521B	
1521	S. College Ave.		X		03 : 29	1935	Domestic Single		Tudor Revival	Red Brick	84	520	
1603	S. College Ave.		X		03 : 28	1935	Domestic Single		Colonial Revival	Red Brick	84	519	
1613	S. College Ave.		X		03 : 27	1935	Domestic Single		Tudor Revival	Brick	84	518	
1614	S. College Ave.		X			1940	Domestic Single		Colonial Revival	Brick/Synthetic Siding	84	523	
1619	S. College Ave.		X		03 : 26	1940	Domestic Single		Colonial Revival	Stone	84	517	
1620	S. College Ave.		X			1950	Domestic Single		Ranch	Brick	84	524	
1702	S. College Ave.		X			1950	Domestic Single		Colonial Revival	Brick	84	525	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type		Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M			SL	Roll	Frame	Slide				
1708	S. College Ave.	X				04:02	Domestic Single			Montlery	Brick	84	526	
1709	S. College Ave.		X				Domestic Single			Colonial Revival	Brick	84	516A	
1709	S. College Ave. (rear)				X		Domestic Single				Wood	84	516B	
1717	S. College Ave.	X				03:25	Domestic Single			Tudor Revival	Brick	84	515A	
1717	S. College Ave.		X				Domestic Single			Tudor Revival	Brick	84	515B	
1718	S. College Ave.			X			Domestic Single			Colonial Revival	Brick	84	527	
1720	S. College Ave.	X				04:03	Domestic Single			Tudor Revival	Red Brick	84	528	
1804	S. College Ave.	X				04:04	Domestic Single			Classical Revival	Brick	84	529A	
1804	S. College Ave. (rear)		X				Domestic Auxillary	Garage Apartment			Wood	84	529B	
1816	S. College Ave.	X				04:05	Domestic Single			Colonial Revival	Red Brick	84	530	
1882	S. College Ave.	X				03:24	Domestic Single			Montlery	Brick	84	514	
1900	S. College Ave.		X				Commercial			Colonial Revival	Brick	95	940A	
1931	S. College Ave.		X				Commercial			Tudor Revival	Yellow Brick	95	939	
2000	S. College Ave.		X				Commercial				Brick	95	941	
2000	S. College Ave.		X				Domestic Auxillary	Garage Apartment			Synthetic Siding	95	940B	
2015	S. College Ave.	X				05:10	Commercial			Colonial Revival	Red Brick	95	938	
100 -200blk.	W. Dobbs St.	X				01:19	Infrastructure and Utilities	Street			Red Brick	70	73	
116 -18	W. Dobbs St.			X			Domestic Single				Brick	70	11	
125	W. Dobbs St.		X				Domestic Single				Wood	70	10A	
125	W. Dobbs St. (rear)		X				Domestic Single			Ranch	Wood	70	10B	
127 &	W. Dobbs St.		X				Domestic Single	Garage Apartment			Yellow Brick	70	9	
212	W. Dobbs St.	X				01:03	Domestic Single	Cross Gabled Bungalow			Brick	70	12	
301	W. Dobbs St.		X				Domestic Single			Tudor Revival	Brick	70	13A	
302	W. Dobbs St.		X				Domestic Single			Colonial Revival	Brick	70	8	
302	W. Dobbs St. (rear)	X				01:04	Domestic Single			Classical Revival	Red Brick	70	13B	
305	W. Dobbs St.	X					Domestic Auxillary	Garage Apartment			Red Brick/Wood	70	138	
309	W. Dobbs St.	X					Domestic Single			Colonial Revival	Brick	70	7	
310	W. Dobbs St.	X					Domestic Single			Colonial Revival	Yellow Brick	70	6	
310	W. Dobbs St. (rear)	X					Domestic Auxillary	Garage Apartment			Brick	70	14A	
318	W. Dobbs St.		X				Domestic Single			Colonial Revival	Brick	70	14B	
319	W. Dobbs St.		X				Domestic Single				Red Brick/Asbestos	70	15	
319	W. Dobbs St. (rear)		X				Domestic Auxillary	Garage Apartment			Red Brick/Wood	70	5A	
			X				Domestic Auxillary	Garage Apartment			T-111	70	5B	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority				Photo Reference		Date	Identification			Exterior Materials	Map No.	I.D. No.		
Street Number and Name		H	S	M	S	L	Roll		Frame	Slide	Property Type				Subtype	Stylistic Influence
1119	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	242
1120	S. Donnybrook Ave.			X						1925	Domestic Single	Front Gabled Bungalow		Wood	80	299
1121	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	241
1123	S. Donnybrook Ave.					X				1935	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Red Brick	79	240
1205	S. Donnybrook Ave.			X						1945	Domestic Single			Red Brick	79	239
1209	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	238
1210	S. Donnybrook Ave.			X						1940	Domestic Single	Cross Gabled Bungalow		Yellow Brick	80	300
1215	S. Donnybrook Ave.			X						1940	Domestic Auxilliary	Garage Apartment		Wood	79	237
1219	S. Donnybrook Ave.			X						1935	Domestic Single	Side Gabled Bungalow	Colonial Revival	Synthetic Siding	79	236
1222	S. Donnybrook Ave.	X					02	25		1935	Domestic Single		Tudor Revival	Red Brick	80	301
1228	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick/Wood	80	302
1308	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	80	303
1313	S. Donnybrook Ave.			X						1935	Domestic Single		Colonial Revival	Brick	79	235
1319	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	234
1320	S. Donnybrook Ave.					X				1955	Domestic Single	Side Gabled Bungalow	Ranch	Red Brick	80	304
1323	S. Donnybrook Ave.					X				1920	Domestic Single		Tudor Revival	Brick	79	233
1326	S. Donnybrook Ave.			X						1940	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Red Brick	80	305
1400 blk.	S. Donnybrook Ave.			X						1940	Domestic Single		Tudor Revival	Brick	80	307
1402	S. Donnybrook Ave.			X						1940	Domestic Single		Minimal	Brick	80	306
1403	S. Donnybrook Ave.					X				1940	Domestic Single			Vinyl Siding	79	232
1405	S. Donnybrook Ave.			X						1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	231
1409	S. Donnybrook Ave.			X						1935	Domestic Single		Colonial Revival	Brick	79	230
1420	S. Donnybrook Ave.	X					02	26		1945	Domestic Single		Colonial	Stone	80	308
1421	S. Donnybrook Ave.			X						1945	Domestic Single		Colonial	Stone	79	229
1424	S. Donnybrook Ave.			X						1940	Domestic Single		Colonial Revival	Brick	80	309
1501	S. Donnybrook Ave.			X						1940	Domestic Single			Red Brick	84	479
1504	S. Donnybrook Ave.			X						1940	Domestic Single		Colonial Revival	Brick	80	310
1600	S. Donnybrook Ave.			X						1940	Domestic Single		Colonial Revival	Brick	80	311
1800 blk.	S. Donnybrook Ave.			X						1945	Domestic Single			Red Brick	83A	455
1808-10	S. Donnybrook Ave.			X						1945	Domestic Multiple	Duplex		Brick	83A	456
1900-02	S. Donnybrook Ave.			X						1945	Domestic Multiple	Duplex		Yellow Brick	98	990
1904-06	S. Donnybrook Ave.					X				1945	Domestic Multiple	Duplex		Red Brick	98	991

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority	Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Mcp No.	I.D. No.
						Subtype					
1908-10	S. Donnybrook Ave.	X		1945	Domestic Multiple	Duplex		Yellow Brick	98	992	
1912-14	S. Donnybrook Ave.	X		1945	Domestic Multiple	Duplex		Red Brick	98	993	
1916-18	S. Donnybrook Ave.	X		1945	Domestic Multiple	Duplex		Red Brick	98	994	
1920-22	S. Donnybrook Ave.	X		1945	Domestic Multiple	Duplex		Red Brick	98	995	
2300 blk.	S. Donnybrook Ave.	X	07:21	1917	Funerary	Cemetery		Stone	968	1286	
2602	S. Donnybrook Ave.	X		1950	Domestic Single			Yellow Brick	103	1275	
100 blk.	E. Eighth St.	X		1945	Commercial	1-Part Commercial Block		Red Brick	95	943	
100 blk.	E. Eighth St.	X		1945	Commercial	1-Part Commercial Block		Red Brick	95	944	
400-02	E. Eighth St.	X		1945	Domestic Multiple	Duplex	Ranch	Yellow Brick	98	962	
401	E. Eighth St.	X		1945	Domestic Multiple	Duplex	Ranch	Red Brick	98	961	
404-06	E. Eighth St.	X		1945	Domestic Multiple	Duplex		Red Brick	98	963	
408-10	E. Eighth St.	X		1945	Domestic Multiple	Duplex		Red Brick	98	964	
409	E. Eighth St.	X		1955	Domestic Single		Ranch	Red Brick	98	960	
412-14	E. Eighth St.	X		1945	Domestic Multiple	Duplex		Yellow Brick	98	965	
415	E. Eighth St.	X		1955	Domestic Single		Ranch	Red Brick	98	959	
416-18	E. Eighth St.	X		1945	Domestic Multiple	Duplex		Red Brick	98	966	
420-22	E. Eighth St.	X		1945	Domestic Multiple	Duplex		Red Brick	98	967	
421	E. Eighth St.	X		1955	Domestic Single		Ranch	Red Brick	98	958	
427	E. Eighth St.	X		1955	Domestic Single		Ranch	Red Brick	98	957	
503	E. Eighth St.	X		1955	Domestic Single			Yellow Brick	98	956	
509	E. Eighth St.	X		1955	Domestic Single		Ranch	Red Brick	98	955	
518	E. Eighth St.	X		1945	Domestic Single		Ranch	Wood/Red Brick	98	968	
519	E. Eighth St.	X		1950	Domestic Single			Mixed Brick	98	954	
812	E. Eighth St.	X		1955	Domestic Auxiliary	Garage Apartment		Wood	98	969	
817	E. Eighth St.	X		1950	Domestic Single			Yellow Brick/Asbestos	98	953	
911	E. Eighth St.	X		1950	Domestic Single		Ranch	Red Brick	99	1117	
914	E. Eighth St.	X		1950	Domestic Single			Synthetic Siding	99	1118	
915	E. Eighth St.	X		1950	Domestic Single		Ranch	Red Brick	99	1116	
920	E. Eighth St.	X		1910	Domestic Single			Synthetic Siding	99	1119	
924	E. Eighth St.	X		1955	Domestic Single			Red Brick	99	1120	
930	E. Eighth St.	X		1950	Domestic Single			Synthetic Siding	99	1121	
933	E. Eighth St.	X		1950	Domestic Single		Ranch	Red Brick	99	1115	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority		Photo Reference	Date	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		HSM	M/SL			Property Type	Subtype				
1009	E. Eighth St.		X		1940	Domestic Single		Colonial Revival	Asbestos	99	1114
209	W. Eighth St.		X		1935	Domestic Single		Tudor Revival	Brick	95	929
302	W. Eighth St.		X		1935	Domestic Single		Colonial Revival	Brick	95	923
321	W. Eighth St.		X		1948	Domestic Single		Colonial Revival	Stone	95	928A
321	W. Eighth St. (rear)		X		1960	Domestic Auxillary	Garage Apartment		Brick	95	928B
324	W. Eighth St.		X		1940	Domestic Single		Colonial Revival	Red Brick	95	924
400 blk.	W. Eighth St.		X		1935	Domestic Single		Colonial Revival	Brick	95	926
405	W. Eighth St.		X		1935	Domestic Single		Colonial Revival	Wood	95	927
418	W. Eighth St.		X		1935	Domestic Single		Colonial Revival	Wood	95	925
600 blk.	W. Eighth St.		X		1940	Domestic Single		Tudor Revival	Brick	94	849
600 blk.	W. Eighth St.		X		1940	Domestic Single		Tudor Revival	Mixed Brick	94	853
604	W. Eighth St.		X		1940	Domestic Single			Brick/synthetic siding	94	846
605	W. Eighth St.		X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	94	854
608	W. Eighth St.		X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	94	847
624	W. Eighth St.		X		1950	Domestic Single			Wood	94	848
631	W. Eighth St.		X		1940	Domestic Single	Cross Gabled Bungalow	Mihndal	Red Brick	94	852
632	W. Eighth St.		X		1955	Domestic Single			Stone	94	850
633	W. Eighth St.		X		1955	Domestic Single		Colonial Revival	Red Brick	94	851
900 blk.	W. Eighth St.		X		1950	Domestic Single		Ranch	Brick	93A	746
900 blk.	W. Eighth St.		X		1940	Domestic Single			Stone	93A	747
926	W. Eighth St.		X		1950	Domestic Single		Colonial Revival	Wood	93A	739
1000 blk.	W. Eighth St.		X		1950	Domestic Single		Colonial Revival	Red Brick	93A	745
1002	W. Eighth St.		X		1950	Domestic Single			Red Brick	93A	740
1011	W. Eighth St.		X		1945	Domestic Single			Stone	93A	744
1012	W. Eighth St.		X		1950	Domestic Single		Colonial Revival	Wood/Yellow Brick	93A	741
1015	W. Eighth St.		X		1940	Domestic Single			Yellow Brick	93A	743
1020	W. Eighth St.		X		1945	Domestic Single			Wood	93A	742
1612	S. Englewood Ave.		X		1950	Domestic Single	Side Gabled Bungalow		Synthetic siding	86	718
1620	S. Englewood Ave.		X		1950	Domestic Single	Side Gabled Bungalow		Aluminum	86	719
1624	S. Englewood Ave.		X		1945	Domestic Single			Aluminum	86	720
1628	S. Englewood Ave.		X		1940	Domestic Single	Side Gabled Bungalow		Wood	86	721
1632	S. Englewood Ave.		X		1940	Domestic Single	Cross Gabled Bungalow		Wood	86	722

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority		Photo Reference		Date	Property Type		Identification		Stylistic Influence	Exterior Materials		Map No.	I.D. No.
Street Number and Name	HSM/MSL	SL	Roll	Frame	Slide		Property Type	Subtype	Subtype	Stylistic Influence		Material	Material		
1712	S. Englewood Ave.			X		1950	Domestic Single				Colonial Revival	Wood	Wood	86	723
121	W. Fair Ln.			X		1950	Domestic Single				Colonial Revival	Red Brick	Red Brick	122	1240
300 blk.	W. Fair Ln.			X		1950	Infrastructure and Utilities	Water Channel				Concrete	Concrete	122	1241
1200 blk.	S. Fannin Ave.			X		1935	Domestic Single	Cross Gabled Bungalow				Stone/Wood	Stone/Wood	79	244
1206	S. Fannin Ave.			X		1935	Domestic Single					Wood	Wood	79	1908
1208	S. Fannin Ave.				X	1945	Domestic Single					Synthetic Siding	Synthetic Siding	79	243
401	E. Fifth St.			X		1940	Domestic Single					Yellow Brick	Yellow Brick	83A	414
405	E. Fifth St.			X		1940	Domestic Single					Wood/Red Brick	Wood/Red Brick	83A	415
409	E. Fifth St.			X		1940	Domestic Single					Red Brick	Red Brick	83A	416
413	E. Fifth St.				X	1940	Domestic Single					Yellow Brick	Yellow Brick	83A	417
419	E. Fifth St.			X		1940	Domestic Single				Colonial Revival	Red Brick	Red Brick	83A	418
420	E. Fifth St.				X	1935	Domestic Single	Cross Gabled Bungalow			Tudor Revival	Wood	Wood	83A	420
427	E. Fifth St.			X		1940	Domestic Single					Brick	Brick	83A	419
500 blk.	E. Fifth St.			X		1955	Domestic Single					Synthetic Siding	Synthetic Siding	83A	425
500 blk.	E. Fifth St.				X	1940	Domestic Single					Synthetic Siding	Synthetic Siding	83A	426
501	E. Fifth St.			X		1950	Domestic Single				Ranch	Brick	Brick	83A	421
507	E. Fifth St.				X	1950	Domestic Single				Colonial Revival	Synthetic Siding	Synthetic Siding	83A	422
508	E. Fifth St.			X		1955	Domestic Single				Ranch	Wood	Wood	83A	424
608	E. Fifth St.				X	1955	Domestic Single				Ranch	Wood	Wood	83A	427
315	W. Fifth St.			X		1935	Domestic Single				Tudor Revival	Yellow Brick	Yellow Brick	84	500
318	W. Fifth St.				X	1940	Domestic Single				Tudor Revival	Brick	Brick	84	495
319	W. Fifth St.			X		1935	Domestic Single				Classical Revival	Brick	Brick	84	499
322	W. Fifth St.			X		1940	Domestic Single				Classical Revival	Brick	Brick	84	494
325	W. Fifth St.			X		1935	Domestic Single				Classical Revival	Brick	Brick	84	498
401	W. Fifth St.				X	1940	Domestic Single					Brick	Brick	84	497
404	W. Fifth St.			X		1935	Domestic Single				Spanish Colonial	Stone	Stone	84	493
500 blk.	W. Fifth St.			X		1925	Domestic Single					Wood	Wood	85	564
504	W. Fifth St.			X		1935	Domestic Single	Front Gabled Bungalow				Red Brick	Red Brick	85	566
508	W. Fifth St.			X		1940	Domestic Single	Front Gabled Bungalow			Tudor Revival	Synthetic Siding	Synthetic Siding	85	565
513	W. Fifth St.			X		1925	Domestic Single	Cross Gabled Bungalow				Wood	Wood	85	559A
513	W. Fifth St. (rear)			X		1940	Domestic Auxiliary	Garage Apartment				Wood	Wood	85	559B
515	W. Fifth St.			X		1940	Domestic Single					Wood	Wood	85	558

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M			SL	Property Type	Subtype			
516	W. Fifth St.		X			1940	Domestic Single	Side Gabled Bungalow	Colonial Revival	Brick/Synthetic Siding	85	563
520	W. Fifth St.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	85	562A
520	W. Fifth St. (rear)			X		1940	Domestic Auxiliary	Garage Apartment		Wood	85	562B
528	W. Fifth St.		X			1940	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Synthetic siding	85	561
532	W. Fifth St.		X			1940	Domestic Single	Side Gabled Bungalow		Yellow Brick	85	560
616	W. Fifth St.			X		1940	Domestic Single			Yellow Brick/Synthetic	85	*563
622	W. Fifth St.		X			1940	Domestic Single	Side Gabled Bungalow		Brick	85	*564
702	W. Fifth St.			X		1950	Domestic Single			Brick	85	*565
706	W. Fifth St.		X			1940	Domestic Single			Brick	85	*566
712	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	567
715	W. Fifth St.		X			1950	Domestic Single			Red Brick	85	568
800	W. Fifth St.			X		1950	Domestic Single		Ranch	Yellow Brick	85	569
800 blk.	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	585
800 blk.	W. Fifth St.		X			1950	Domestic Single			Brick	85	589
801	W. Fifth St.		X			1950	Domestic Single		Colonial Revival	Yellow Brick/Wood	85	588
810	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	570
811	W. Fifth St.		X			1950	Domestic Single		Colonial Revival	Red Brick	85	587
814	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	571
818	W. Fifth St.		X			1950	Domestic Single		Colonial Revival	Red Brick/Synthetic	85	572
823	W. Fifth St.		X			1950	Domestic Single		Colonial Revival	Yellow Brick	85	586
826	W. Fifth St.		X			1950	Domestic Single		Ranch	Red Brick	85	573
828	W. Fifth St.		X			1950	Domestic Single		Ranch	Red Brick	85	574
835	W. Fifth St.			X		1950	Domestic Single		Ranch	Red Brick/Wood	85	584
902	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	575
904	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	576
905	W. Fifth St.		X			1950	Domestic Single		Ranch	Stucco	85	583
906	W. Fifth St.			X		1950	Domestic Single		Ranch	Brick	85	577
914	W. Fifth St.		X			1950	Domestic Single		Ranch	Yellow Brick	85	578
918	W. Fifth St.		X			1950	Domestic Single		Ranch	Red Brick	85	579
922	W. Fifth St.			X		1950	Domestic Single		Ranch	Brick	85	580
928	W. Fifth St.		X			1950	Domestic Single		Ranch	Red Brick	85	581
934	W. Fifth St.			X		1950	Domestic Single		Ranch	Wood	85	582

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference		Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M	SL	Roll			Frame	Slide				
1300 blk.	W. Fifth St.				X			Domestic Single				Wood	86	677
1300 blk.	W. Fifth St.				X			Domestic Single				Wood	86	679
1303	W. Fifth St.				X			Domestic Single				Wood	86	681
1307	W. Fifth St.				X			Domestic Single				Wood	86	680
1308	W. Fifth St.				X			Domestic Single				Wood	86	670
1316	W. Fifth St.				X			Domestic Single				Wood	86	671
1320	W. Fifth St.				X			Domestic Single				Wood	86	672
1321	W. Fifth St.				X			Domestic Single				Asbestos	86	678
1402	W. Fifth St.				X			Domestic Single				Wood	86	673
1403	W. Fifth St.				X			Domestic Single				Wood	86	676
1406	W. Fifth St.				X			Domestic Single				Asbestos	86	674
1412	W. Fifth St.				X			Domestic Single				Wood	86	675
117	E. First St.				X			Domestic Single			Ranch	Red Brick	79	201
122 -24	E. First St.				X			Domestic Single			Craftsman	Wood	79	202
123	E. First St.				X			Domestic Single			Ranch	Red Brick/Wood	79	200
126 A-D	E. First St.				X			Domestic Multiple			Apartment	Red Brick	79	203
200 blk.	E. First St.				X			Domestic Auxiliary			Garage Apartment	Wood	79	209
214	E. First St.				X			Domestic Single			Colonial Revival	Brick	79	205
218	E. First St.				X			Domestic Single				Red Brick	79	206
222	E. First St.				X			Domestic Single				Red Brick	79	207
226	E. First St.				X			Domestic Single				Brick	79	208
309	E. First St.				X			Domestic Single			Front Gabled Bungalow	Red Brick	79	199A
309	E. First St. (rear)				X			Domestic Multiple			Duplex	Wood	79	199B
311 &	E. First St.				X			Domestic Single			Colonial Revival	Yellow Brick	79	198
315	E. First St.				X			Domestic Single			Tudor Revival	Red Brick	79	197
319	E. First St.				X			Domestic Single				Wood	79	196
600 blk.	E. First St.				X		03:03	Infrastructure and Utilities			Bridge	Concrete	80	259A
600 blk.	E. First St.				X			Infrastructure and Utilities			Bridge	Concrete	80	259B
615	E. First St.				X			Domestic Single				Brick	80	258
712 -14	E. First St.				X			Domestic Multiple			Duplex	Red Brick	80	261
1216 1/2	E. First St.				X			Domestic Auxiliary			Garage Apartment	Wood	79	204B
112	W. First St.				X		01:29	Domestic Single			Tudor Revival	Red Brick/Stone	79	115

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type		Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M			SL	Property Type	Subtype	Subtype				
200	W. First St.	X			01 : 30	1935	Domestic Single			Tudor Revival	Yellow Brick	79	116	
201	W. First St.			X		1950	Domestic Single				Brick/Wood	79	113	
202 -04	W. First St.		X			1935	Domestic Multiple	Duplex		Tudor Revival	Yellow Brick	79	117	
208	W. First St.		X			1935	Domestic Single			Tudor Revival	Brick	79	118A	
208	W. First St. (rear)		X			1935	Domestic Single			Tudor Revival	Wood	79	118B	
209	W. First St.		X			1940	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Brick	79	112	
214	W. First St.		X			1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Red Brick	79	119	
218	W. First St.		X		01 : 31	1935	Domestic Single			Classical Revival	Yellow Brick	79	120A	
314	W. First St.		X			1935	Domestic Single			Tudor Revival	Red Brick	79	121	
315	W. First St.		X		01 : 27	1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Yellow Brick/Stone	79	111	
322	W. First St.		X			1935	Domestic Single			Tudor Revival	Yellow Brick	79	122A	
322	W. First St. (rear)		X			1935	Domestic Auxiliary	Garage Apartment		Tudor Revival	Yellow Brick	79	122B	
323	W. First St. (rear)		X			1935	Domestic Auxiliary	Garage Apartment		Tudor Revival	Red Brick	79	110B	
323 AB	W. First St.		X			1935	Domestic Multiple	Duplex		Tudor Revival	Red Brick	79	110A	
325	W. First St.		X			1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Yellow Brick	79	109	
400 blk.	W. First St.		X		01 : 28	1935	Domestic Single			Colonial Revival	Red Brick	79	123A	
400 blk.	W. First St. (rear)		X			1950	Domestic Auxiliary	Garage Apartment			Wood	79	123B	
403	W. First St.		X			1935	Domestic Single			Colonial Revival	Brick	79	108	
404	W. First St.		X			1935	Domestic Single			Tudor Revival	Brick	79	124A	
404	W. First St. (rear)		X			1935	Domestic Auxiliary	Garage Apartment			Synthetic siding	79	124B	
412	W. First St.		X			1940	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Brick	79	125	
210 /1216	E. First St. / Fannin Ave.		X			1935	Domestic Multiple	Duplex		Tudor Revival	Brick	79	204A	
2103	S. Fleishel Ave.		X			1940	Domestic Single			Colonial Revival	Wood	99	1124	
2117	S. Fleishel Ave.			X		1935	Domestic Single				Synthetic Siding	99	1125	
200 blk.	E. Ford St.		X			1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Red Brick	79	189	
206 1/2	E. Ford St.		X			1925	Domestic Single	Cross Gabled Bungalow		Craftsman	Wood	79	190A	
214	E. Ford St.		X			1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Wood	79	191	
217	E. Ford St.		X			1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Yellow Brick	79	188	
220	E. Ford St.		X			1935	Domestic Single	Cross Gabled Bungalow			Mixed Brick	79	192	
221	E. Ford St.		X			1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Yellow Brick	79	187	
223	E. Ford St.		X			1935	Domestic Single			Tudor Revival	Yellow Brick	79	186	
300	E. Ford St.			X		1935	Domestic Single			Colonial Revival		79	193	

Tyer, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M				SL	Subtype				
300 blk.	E. Ford St.		X			1945	Domestic Single	Side Gabled Bungalow			Wood	79	183
303	E. Ford St.		X			1935	Domestic Single		Tudor Revival		Yellow Brick	79	185
304	E. Ford St.		X			1925	Domestic Single	Front Gabled Bungalow	Craftsman		Wood	79	194
305	E. Ford St.			X		1945	Domestic Single	Massed Plan Pyramidal			Wood	79	184
308	E. Ford St.			X		1935	Domestic Single				Synthetic Siding	79	195
100	E. Fourth St.		X			1940	Domestic Single				Yellow Brick	84	467
100 blk.	E. Fourth St.		X			1940	Domestic Single				Stone	84	466
102	E. Fourth St.		X			1950	Domestic Single				Red Brick	84	469
108	E. Fourth St.		X			1940	Domestic Single				Red Brick	84	468
215	E. Fourth St.		X		03:08	1940	Domestic Single		Classical Revival		Stone	84	470
223	E. Fourth St.			X		1950	Domestic Single				Stone	84	472
300	E. Fourth St.		X			1940	Domestic Single		Colonial Revival		Red Brick	84	478
305	E. Fourth St.		X			1950	Domestic Single				Red Brick	84	471
306	E. Fourth St.		X			1940	Domestic Single				Brick	84	477
311	E. Fourth St.		X			1950	Domestic Single		Colonial Revival		Brick	84	473
312	E. Fourth St.			X		1940	Domestic Single		Colonial Revival		Synthetic Siding	84	476
318	E. Fourth St.		X			1940	Domestic Single				Brick	84	475
319	E. Fourth St.		X			1950	Domestic Single		Colonial Revival		Brick	84	474
400 blk.	E. Fourth St.		X			1945	Domestic Single				Brick	80	298
401	E. Fourth St.		X			1940	Domestic Single				Red Brick/Synthetic	83A	413
407	E. Fourth St.			X		1940	Domestic Single		Colonial Revival		Wood	83A	412
408	E. Fourth St.		X			1950	Domestic Single				Brick	80	297
412	E. Fourth St.			X		1950	Domestic Single				Red Brick	80	296
500 blk.	E. Fourth St.		X			1940	Domestic Single		Colonial Revival		Wood	80	294
500 blk.	E. Fourth St.		X			1945	Domestic Single				Synthetic Siding	83A	409
503	E. Fourth St.			X		1940	Domestic Single		Colonial Revival		Aluminum	83A	411
509	E. Fourth St.		X			1940	Domestic Single		Colonial Revival		Red Brick	83A	410
512	E. Fourth St.			X		1945	Domestic Single				Yellow Brick	80	295
523	E. Fourth St.		X			1940	Domestic Single	Cross Gabled Bungalow	Minimal		Yellow Brick	83A	408
118	W. Fourth St.		X		03:09	1935	Domestic Single		Tudor Revival		Red Brick	84	484
122	W. Fourth St.		X			1940	Domestic Single				Red Brick	84	485
313 -15	W. Fourth St.		X			1935	Domestic Multiple	Duplex	Tudor Revival		Brick	84	486

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference Roll :frame Slide	Date	Property Type		Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M			S	L	L	U				
319	W. Fourth St.		X			1935	Domestic Single			Colonial Revival	Brick	84	487	
322	W. Fourth St.		X			1935	Domestic Single			Tudor Revival	Wood/Brick	84	490	
325	W. Fourth St.		X			1950	Domestic Single				Brick	84	488	
400	W. Fourth St.		X			1935	Domestic Single			Tudor Revival	Yellow Brick	84	491	
401	W. Fourth St.		X			1935	Domestic Single			Tudor Revival	Brick	84	489	
500 blk.	W. Fourth St.			X		1940	Domestic Single			Colonial Revival	Synthetic Siding	84	492	
512	W. Fourth St.		X			1935	Domestic Single			Tudor Revival	Red Brick	85	537	
518	W. Fourth St.		X			1935	Domestic Single			Minimal	Yellow Brick	85	538	
524	W. Fourth St.		X			1940	Domestic Single			Colonial Revival	Red Brick	85	539	
1024	W. Fourth St.			X		1945	Domestic Single			Ranch	Asbestos	76	650	
1028	W. Fourth St.			X		1945	Domestic Single			Side Gabled Bungalow	Asbestos	76	651	
1100	W. Fourth St.			X		1945	Domestic Single			Side Gabled Bungalow	Asbestos	76	652	
1100 blk.	W. Fourth St.			X		1945	Domestic Single				Asbestos	76	654	
1106	W. Fourth St.		X			1950	Domestic Single			Ranch	Red Brick	76	653	
1114	W. Fourth St.		X			1945	Domestic Single			Side Gabled Bungalow	Synthetic Siding	76	655	
1118	W. Fourth St.		X			1945	Domestic Single				Wood	76	656	
1120	W. Fourth St.		X			1940	Domestic Single				Asbestos	76	657	
1202	W. Fourth St.		X			1940	Domestic Single				Asbestos	76	658	
1206	W. Fourth St.		X			1945	Domestic Single				Wood	76	659	
1228	W. Fourth St.		X			1940	Domestic Single			Cross Gabled Bungalow	Wood	76	660	
1300	W. Fourth St.		X			1950	Domestic Single				Synthetic Siding	76	661	
1304	W. Fourth St.		X			1945	Domestic Single				Wood	76	662	
1308	W. Fourth St.		X			1935	Domestic Single			Front Gabled Bungalow	Wood	76	663A	
1308	W. Fourth St. (rear)		X			1940	Domestic Auxiliary			Garage Apartment	Wood	76	663B	
1310	W. Fourth St.		X			1940	Domestic Single			Cross Gabled Bungalow	Brick	76	664	
1318	W. Fourth St.		X			1950	Domestic Single				Wood	76	665	
1324	W. Fourth St.		X			1900	Domestic Single			Center Passage	Vinyl siding	76	666	
1408	W. Fourth St.		X			1940	Domestic Single				Brick	76	667	
1414	W. Fourth St.		X			1940	Domestic Single				Wood	76	668	
200	W. Glenhaven		X			1950	Domestic Single				Brick	122	1246	
209	W. Glenhaven		X			1950	Domestic Single				Mixed Brick	122	1245	
219	W. Glenhaven		X			1950	Domestic Single				Red Brick	122	1244	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Identification			Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M			Property Type	Subtype					
220	W. Glenhaven	X			07 : 03	1950	Domestic Single		Colonial Revival	Red Brick	122	1247	
229	W. Glenhaven		X			1955	Domestic Single		Colonial Revival	Red Brick	122	1243	
230	W. Glenhaven			X		1955	Domestic Single	Ranch		Brick	122	1248	
309	W. Glenhaven	X			06 : 33,34	1940	Domestic Single		Colonial Revival	Red Brick	122	1242	
310	W. Glenhaven		X			1950	Domestic Single		Colonial	Mixed Brick	122	1249	
600 blk.	W. Glenwood Blvd.			X		1945	Religious	Church	Colonial Revival	Red Brick	85	547A	
600 blk.	W. Glenwood Blvd.			X		1980	Religious	Church		Red Brick	85	547B	
724	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	548	
800	W. Glenwood Blvd.		X			1950	Domestic Single	Front Gabled Bungalow		Asbestos	85	541	
800 -800 1/2	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	551	
800 1/2	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	549	
804	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	550	
806	W. Glenwood Blvd.		X			1950	Domestic Single	Front Gabled Bungalow		Asbestos	85	542	
812	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	552	
816	W. Glenwood Blvd.		X			1950	Domestic Single	Front Gabled Bungalow		Asbestos	85	543	
816 1/2	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	553	
820	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	554	
824	W. Glenwood Blvd.		X			1950	Domestic Single	Side Gabled Bungalow		Asbestos	85	544	
826 1/2	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	555	
834	W. Glenwood Blvd.		X			1950	Domestic Single	Side Gabled Bungalow		Asbestos	85	545	
834 1/2	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	557	
836	W. Glenwood Blvd.		X			1950	Domestic Auxiliary	Garage Apartment		Asbestos	85	556	
904	W. Glenwood Blvd.		X			1950	Domestic Single	Cross Gabled Bungalow		Asbestos	85	546	
400 blk.	E. Haden St.		X			1945	Domestic Single			Vinyl Siding	97	1313	
401	E. Haden St.		X			1950	Domestic Single			Wood/Asbestos	97	1320	
402	E. Haden St.		X			1945	Domestic Single			Asbestos	97	1311	
407	E. Haden St.		X			1945	Domestic Single			Wood	97	1319	
408	E. Haden St.		X			1945	Domestic Single			Vinyl Siding	97	1312	
411	E. Haden St.		X			1945	Domestic Single			Wood	97	1318	
415	E. Haden St.		X			1945	Domestic Single			Vinyl Siding	97	1317	
417	E. Haden St.		X			1945	Domestic Single			Vinyl Siding	97	1316	
420	E. Haden St.		X			1945	Domestic Single			Wood	97	1314	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority				Photo Reference		Date	Identification			Exterior Materials	Map No.	I.D. No.	
Street Number and Name		H	SM	M	SL	Roll	Frame		Slide	Property Type	Subtype				Stylistic Influence
421	E. Haden St.			X					1945	Domestic Single			Asbestos	97	1315
626	E. Haden St.			X					1950	Domestic Single			Brick	97	1327
627	E. Haden St.			X					1945	Domestic Single			Brick	97	1310
632	E. Haden St.			X					1950	Domestic Single			Brick	97	1326
633	E. Haden St.				X				1945	Domestic Single			Brick	97	1309
703	E. Haden St.				X				1945	Domestic Single			Brick	97	1308
704	E. Haden St.				X				1955	Domestic Single			Brick	97	1325
709	E. Haden St.				X				1945	Domestic Auxiliary	Garage Apartment		Wood	97	1307
606	W. Hamvasy Ln.	X				06	04		1950	Domestic Single		Colonial Revival	Yellow Brick	105	1196
700 blk.	W. Hamvasy Ln.			X					1950	Religious	Church		Stone	96	1147
709	W. Hamvasy Ln.				X				1950	Domestic Single		Colonial Revival	Brick	96	1156
715	W. Hamvasy Ln.			X					1950	Domestic Single			Asbestos	96	1155
718	W. Hamvasy Ln.			X					1950	Domestic Single		Ranch	Pink Brick	96	1148
800 blk.	W. Hamvasy Ln.	X				05	20		1940	Infrastructure and Utilities	Water Channel		Stone	96	1154
802	W. Hamvasy Ln.			X					1940	Domestic Single			Yellow Brick/Stone	96	1149
808	W. Hamvasy Ln.			X					1955	Domestic Single			Red Brick	96	1150
815	W. Hamvasy Ln.				X				1955	Domestic Single		Ranch	Wood	96	1153
818	W. Hamvasy Ln.			X					1950	Domestic Single		Ranch	Mixed Brick	96	1151
824	W. Hamvasy Ln.			X					1955	Domestic Single		Ranch	Mixed Brick	96	1152
1901	S. Henderson Dr.				X				1945	Domestic Single			Wood	98	996
1903	S. Henderson Dr.			X					1950	Domestic Single		Ranch	Red Brick	98	997
1905	S. Henderson Dr.			X					1945	Domestic Single		Colonial Revival	Brick	98	998
1907	S. Henderson Dr.			X					1950	Domestic Single		Ranch	Red Brick	98	999
1909	S. Henderson Dr.			X					1950	Domestic Single		Ranch	Red Brick	98	1000
1911	S. Henderson Dr.			X					1950	Domestic Single		Ranch	Red Brick	98	1001
1913	S. Henderson Dr.			X					1950	Domestic Single		Ranch	Red Brick	98	1002
1300 blk.	S. Highland Ave.				X				1955	Domestic Single			Aluminum	80	407
1535	S. Highland Ave.				X				1955	Domestic Single			Red Brick	80	406
1900 blk.	S. Hilltop Dr.			X					1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	94	868
1904	S. Hilltop Dr.	X				04	20		1945	Domestic Single		Colonial Revival	Brick	94	865
1908	S. Hilltop Dr.				X				1940	Domestic Single		Colonial Revival	Brick/Synthetic Siding	94	866
1909	S. Hilltop Dr.	X				04	22		1945	Domestic Single		Colonial Revival	Wood	94	864

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority	Photo Reference	Date	Identification			Exterior Materials	Map No.	I.D. No.
					Property Type	Subtype	Stylistic Influence			
1910	S. Hilltop Dr.	X		1945	Domestic Single		Colonial Revival	Yellow Brick	94	867
1924	S. Hilltop Dr.	X		1950	Domestic Single		Colonial Revival	Brick	94	869
1925	S. Hilltop Dr.	X		1950	Domestic Single		Tudor Revival	Yellow Brick/Synthetic	94	863
2000	S. Hilltop Dr.	X		1940	Domestic Single			Brick	94	870
2003	S. Hilltop Dr.	X	04:21	1950	Domestic Single		Colonial Revival	Brick	94	862A
2003	S. Hilltop Dr. (rear)	X		1950	Domestic Auxiliary	Garage Apartment	Colonial Revival	Brick	94	862B
2006	S. Hilltop Dr.	X		1945	Domestic Single			Yellow Brick	94	871
2013	S. Hilltop Dr.	X		1945	Domestic Single		Colonial Revival	Red Brick	94	861A
2014	S. Hilltop Dr. (rear)	X	04:23	1950	Domestic Auxiliary	Garage Apartment		Red Brick	94	861B
2017	S. Hilltop Dr.	X		1950	Domestic Single		Colonial Revival	Yellow Brick	94	872
2025	S. Hilltop Dr.	X		1950	Domestic Single		Colonial Revival	Brick	94	860
2106	S. Hilltop Dr.	X		1950	Domestic Single		Colonial Revival	Brick	94	859
2114	S. Hilltop Dr.	X		1950	Domestic Single		Monterey	Brick	94	873
2114	S. Hilltop Dr. (rear)	X		1950	Domestic Single		Colonial Revival	Brick	94	874A
400 blk.	E. Hudson St.	X		1950	Domestic Auxiliary	Garage Apartment		Brick	94	874B
405	E. Hudson St.	X		1950	Domestic Single			Red Brick	97	1305
409	E. Hudson St.	X		1940	Domestic Single			Asbestos	97	1304
415	E. Hudson St.	X		1945	Domestic Single			Red Brick	97	1303
416	E. Hudson St.	X		1940	Domestic Single			Red Brick	97	1303
416	E. Hudson St.	X		1950	Domestic Single			Asbestos	97	1302
421	E. Hudson St.	X		1940	Domestic Single			Brick	97	1306
627	E. Hudson St.	X		1955	Domestic Single			Asbestos	97	1301
630	E. Hudson St.	X		1955	Domestic Single			Red Brick	97	1300
632	E. Hudson St.	X		1945	Domestic Single		Ranch	Brick	97	1295
702	E. Hudson St.	X		1945	Domestic Single			Red Brick/Wood	97	1296
705	E. Hudson St.	X		1940	Domestic Single			Brick	97	1297
710	E. Hudson St.	X		1940	Domestic Single		Colonial Revival	Brick	97	1299
2000 blk.	S. Jacksonville Hwy.	X		1950	Domestic Single			Red Brick	97	1298
2115	S. Jacksonville Hwy.	X		1945	Domestic Single			Concrete Block	95	931
2260	S. Jacksonville Hwy.	X		1950	Domestic Single		Ranch	Brick	95	930
2300 blk.	S. Jacksonville Hwy.	X		1950	Domestic Single		Ranch	Red Brick	96	1183
2302	S. Jacksonville Hwy.	X		1950	Domestic Single		Ranch	Red Brick	96	1181
		X		1955	Domestic Single		Ranch	Red Brick	96	1184

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Stylistic Influence				
2307	S. Jacksonville Hwy.			X		1955	Domestic Single				Brick/Wood	96	1176
2307	S. Jacksonville Hwy.	X				1950	Domestic Single				Red Brick	96	1182
2316	S. Jacksonville Hwy.		X			1955	Domestic Single		Ranch		Red Brick	96	1185
2329	S. Jacksonville Hwy.	X				1950	Domestic Single				Wood	96	1180
2400 blk.	S. Jacksonville Hwy.		X			1955	Domestic Single		Colonial Revival		Red Brick	96	1177
2402	S. Jacksonville Hwy.			X		1955	Domestic Single				Mixed Brick	96	1186
2411	S. Jacksonville Hwy.			X		1925	Domestic Single		Ranch		Wood	96	1179
2421	S. Jacksonville Hwy.	X				1950	Domestic Single		Craftsman		Mixed Brick	96	1178
1800	S. Jarrel Ave.			X		1950	Domestic Single		Colonial Revival		Yellow Brick	83A	437
1801	S. Jarrel Ave.	X				1950	Domestic Single				Red Brick	83A	436
1803	S. Jarrel Ave.	X				1950	Domestic Single				Red Brick	83A	435
1804	S. Jarrel Ave.	X				1950	Domestic Single				Brick	83A	438
1805	S. Jarrel Ave.	X				1950	Domestic Single				Red Brick	83A	434
1806	S. Jarrel Ave.			X		1950	Domestic Single				Red Brick	83A	439
1809	S. Jarrel Ave.	X				1950	Domestic Single				Red Brick	83A	433
1810	S. Jarrel Ave.		X			1950	Domestic Single				Brick	83A	440
1824	S. Jarrel Ave.			X		1950	Domestic Single		Ranch		Yellow Brick	98	1069
1826	S. Jarrel Ave.	X				1935	Domestic Single		Tudor Revival		Brick	98	1068
1900	S. Jarrel Ave.	X				1935	Domestic Single		Tudor Revival		Pink Brick	98	1070
1900 blk.	S. Jarrel Ave.			X		1940	Domestic Single		Colonial Revival		Synthetic siding	98	1074
1905	S. Jarrel Ave.			X		1995	Domestic Single	Cross Gabled Bungalow	Craftsman		Synthetic siding/Red	98	1097
1908	S. Jarrel Ave.		X			1925	Domestic Single				Red Brick	98	1071A
1912	S. Jarrel Ave.	X				1950	Domestic Single				Red Brick	98	1072
1915	S. Jarrel Ave.	X				1950	Domestic Single				Brick	98	1096
1918	S. Jarrel Ave. (rear)			X		1925	Domestic Auxiliary	Garage Apartment			Wood	98	1071B
1918	S. Jarrel Ave.	X				1930	Domestic Single	Front Gabled Bungalow			Yellow Brick	98	1073
1919	S. Jarrel Ave.			X		1935	Domestic Single				Synthetic siding	98	1095
1925	S. Jarrel Ave.	X				1945	Domestic Single				Yellow Brick/Synthetic	98	1094
1929	S. Jarrel Ave.	X				1950	Domestic Single				Yellow Brick	98	1093
2000	S. Jarrel Ave.	X				1950	Domestic Single		Colonial Revival		Red Brick/Wood	98	1075
2003	S. Jarrel Ave.			X		1950	Domestic Single		Ranch		Yellow Brick	98	1092
2006	S. Jarrel Ave.	X				1935	Domestic Single		Tudor Revival		Yellow Brick	98	1076

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Priority			Photo Reference	Date	Property Type	Identification			Exterior Materials	Map No.	I.D. No.
	H	S	M				Roll	Frame	Slide			
2007 S. Jarrel Ave.				X		1935	Domestic Single	Front Gabled Bungalow	Tudor Revival	Yellow Brick/Stucco	98	1091
2010 S. Jarrel Ave.		X				1950	Domestic Single			Red Brick	98	1078
2016 S. Jarrel Ave.			X		05 : 15	1940	Domestic Single			Yellow Brick	98	1077
2017 S. Jarrel Ave.				X		1950	Domestic Single		Tudor Revival	Yellow Brick	98	1090
2021 S. Jarrel Ave.				X		1950	Domestic Single			Red Brick	98	1089
2100 S. Jarrel Ave.		X				1935	Domestic Single		Tudor Revival	Red Brick/Stone	98	1079
2100 blk. S. Jarrel Ave.			X			1940	Domestic Single		Tudor Revival	Mixed Brick	98	1088
2103 S. Jarrel Ave.				X		1935	Domestic Single			Synthetic siding	98	1080
2107 S. Jarrel Ave.		X				1940	Domestic Single			Wood	98	1087
2111 S. Jarrel Ave.			X			1940	Domestic Single			Brick	98	1086
2112 S. Jarrel Ave.				X	05 : 16	1940	Domestic Single			Brick	98	1085
2112 S. Jarrel Ave. (rear)		X				1940	Domestic Auxiliary	Garage Apartment	Colonial Revival	Stone	98	1081A
2116 S. Jarrel Ave.			X			1935	Domestic Single			Wood	98	1081B
2119 S. Jarrel Ave.				X		1940	Domestic Single			Wood	98	1082
2120 S. Jarrel Ave.				X		1935	Domestic Single		Tudor Revival	Red Brick	98	1084
1810 S. Kennedy Ave.				X		1955	Domestic Single			Brick	98	1083
1814 S. Kennedy Ave.		X				1955	Domestic Single			Brick	94	845
1818 S. Kennedy Ave.			X			1950	Domestic Single		Ranch	Red Brick	94	844
1900 blk. S. Kennedy Ave.			X		04 : 13	1950	Domestic Single	School		Asbestos	94	843
1906 S. Kennedy Ave.		X				1945	Domestic Single		Colonial Revival	Yellow Brick	93A	783
2014 S. Kennedy Ave.			X			1950	Domestic Single			Wood	94	841
2210 S. Kennedy Ave.			X			1955	Domestic Single			Asbestos	94	842
2218 S. Kennedy Ave.		X				1935	Domestic Single		Ranch	Wood	94	840
2222 S. Kennedy Ave.			X			1955	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	94	839
2308 S. Kennedy Ave.		X				1950	Domestic Single		Ranch	Red Brick	93B	830
2314 S. Kennedy Ave.		X				1940	Domestic Single	Front Gabled Bungalow		Stone	93B	831
2318 S. Kennedy Ave.			X			1950	Domestic Single			Red Brick	93B	832
2404 S. Kennedy Ave.		X				1950	Domestic Single		Ranch	Brick/Wood	93B	833
2417 S. Kennedy Ave.		X				1950	Domestic Single		Colonial Revival	Wood	93B	834
215 E. Lake St.			X			1950	Domestic Single	Side Gabled Bungalow		Stone/Synthetic Siding	93B	835
										Red Brick	93B	829
										Wood	79	182

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane F. Williams & Associates

Street Number and Name	Address	HSM	M	S	L	Photo Reference Roll :Frame Slide	Date	Property Type	Identification Subtype	Stylistic Influence	Exterior Materials	Map No.	I.D. No.
219	E. Lake St.					X	1930	Domestic Single	Front Gabled Bungalow		Brick	79	181
223	E. Lake St.					X	1930	Domestic Single	Front Gabled Bungalow		Yellow Brick	79	180
300 blk.	E. Lake St.					X	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	177
301	E. Lake St.					X	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	179
305	E. Lake St.					X	1935	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Yellow Brick	79	178
405	E. Lake St.					X	1940	Domestic Auxillary	Garage Apartment		Stone	80	257
409	E. Lake St.					X	1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	80	256
517	E. Lake St.					X	1940	Domestic Single			Red Brick/Wood	80	255
525	E. Lake St.					X	1935	Domestic Single			Brick/Wood	80	254
600 blk.	E. Lake St.					X	02:35	Infrastructure and Utilities	Drainage Channel		Stone	80	253
800 blk.	E. Leard St.					X	1940	Domestic Single	Front Gabled Bungalow		Wood	97A	1357
810	E. Leard St.					X	1955	Domestic Single			Asbestos	97A	1356
100 -300blk.	W. Lindsey Ln.					X	01:18	Infrastructure and Utilities	Street		Red Brick	70	71
100 blk.	W. Lindsey Ln.					X	1935	Infrastructure and Utilities	Drainage Channel		Stone	70	24
116	W. Lindsey Ln.					X	1925	Domestic Single			Brick	70	22A
116	W. Lindsey Ln. (rear)					X	1925	Domestic Auxillary	Garage Apartment		Wood	70	22B
117	W. Lindsey Ln.					X	1925	Domestic Single			Stucco	70	21
121	W. Lindsey Ln.					X	01:07	Domestic Single			Stucco	70	20
204	W. Lindsey Ln.					X	01:09	Domestic Single	Four Square		Wood	70	23A
204	W. Lindsey Ln. (rear)					X	1940	Domestic Auxillary			Wood	70	23B
207	W. Lindsey Ln.					X	1940	Domestic Single			Synthetic Siding	70	19
208	W. Lindsey Ln.					X	1930	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Red Brick	70	25
212	W. Lindsey Ln.					X	1930	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick/Stucco	70	26
300 blk.	W. Lindsey Ln.					X	01:05	Infrastructure and Utilities	Drainage Channel		Stone	70	18A
300 blk.	W. Lindsey Ln.					X	1900	Domestic Single			Synthetic Siding	70	27
300 blk.	W. Lindsey Ln.					X	1935	Infrastructure and Utilities	Headwall		Stone	70	18B
305	W. Lindsey Ln.					X	1940	Domestic Auxillary	Garage Apartment		Brick	70	17
311	W. Lindsey Ln.					X	1945	Domestic Single			Wood/Yellow Brick	70	16
0	E. Loflin St.					X	1940	Domestic Single			Asbestos	97	1329
0	E. Loflin St.					X	1945	Domestic Single			Asbestos	97	1330
400 blk.	E. Loflin St.					X	1950	Domestic Single			Asbestos	103	1376
402	E. Loflin St.					X	1945	Domestic Single			Asbestos	97	1328

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority	Photo Reference	Date	Identification			Exterior Materials	Mcp No.	I.D. No.
					Property Type	Subtype	Stylistic Influence			
423	E. Loffin St.		X	1950	Domestic Single			Wood	103	1377
626	E. Loffin St.	X		1955	Domestic Single			Red Brick	97	1321
630	E. Loffin St.		X	1955	Domestic Single			Red Brick	97	1322
700	E. Loffin St.	X		1955	Domestic Single			Brick/Wood	97	1323
708	E. Loffin St.		X	1955	Domestic Single			Wood	97	1324
100 -400blk.	W. Mockingbird Ln.	X	01 :26	1935	Infrastructure and Utilities	Street		Red Brick	79	251
100 blk.	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	100
110	W. Mockingbird Ln.	X		1935	Domestic Multiple	Apartment		Brick	79	98A
110	W. Mockingbird Ln.	X		1935	Domestic Multiple	Garage Apartment		Wood	79	98B
113	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	97A
113	W. Mockingbird Ln.	X		1935	Domestic Auxiliary	Garage Apartment	Tudor Revival	Wood	79	97B
114 -16	W. Mockingbird Ln.	X		1935	Domestic Multiple	Duplex	Tudor Revival	Yellow Brick	79	99A
114 -16	W. Mockingbird Ln.	X		1935	Domestic Auxiliary	Garage Apartment		Asbestos	79	99B
119	W. Mockingbird Ln.	X	01 :25	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	96
202	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Red Brick	79	101
203	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	95
206	W. Mockingbird Ln.	X	01 :21	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	102
207	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick/Stucco	79	94A
207	W. Mockingbird Ln.	X		1935	Domestic Auxiliary	Garage Apartment		Wood	79	94B
210	W. Mockingbird Ln.	X	01 :22	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	103
213	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	93
219 AB	W. Mockingbird Ln.	X	01 :24	1935	Domestic Multiple	Duplex	Tudor Revival	Red Brick	79	92
314	W. Mockingbird Ln.	X	01 :23	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	104
315	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	91
316	W. Mockingbird Ln.	X		1935	Domestic Single			Brick	79	105
319	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	90
322	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	106
325	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	89
328	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	107A
328	W. Mockingbird Ln.	X		1935	Domestic Auxiliary	Garage Apartment		Brick	79	107B
403	W. Mockingbird Ln.	X		1935	Domestic Single	Side Gabled Bungalow	Tudor Revival	Brick	79	88
405	W. Mockingbird Ln.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	87

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
	HSM	M	SL				Subtype	Subtype				
2205 S. New Copeland Rd.	X			07:24	1935	Domestic Single			Tudor Revival	Red Brick	97	1345
2214 S. New Copeland Rd.		X			1935	Domestic Single			Tudor Revival	Synthetic Siding	97	1346
2215 S. New Copeland Rd.	X			07:23	1935	Domestic Single			Tudor Revival	Brick	97	1344
2220 S. New Copeland Rd.		X			1940	Domestic Single			Colonial Revival	Brick	97	1347
2304 S. New Copeland Rd.		X			1940	Domestic Single			Colonial Revival	Brick	97	1348
2308 S. New Copeland Rd.			X		1955	Domestic Single				Wood/Red Brick	97	1349
2311 S. New Copeland Rd.	X			07:22	1935	Domestic Single			Tudor Revival	Brick	97	1343
2318 S. New Copeland Rd.			X		1955	Domestic Single				Brick	97	1350
2402 S. New Copeland Rd.		X			1940	Domestic Single			Colonial Revival	Yellow Brick	97	1351A
2402 AB S. New Copeland Rd.			X		1960	Domestic Auxiliary	Garage Apartment			Wood	97	1351B
2403 S. New Copeland Rd.		X			1945	Domestic Single				Brick	97	1342
2410 S. New Copeland Rd.			X		1950	Domestic Single				Synthetic Siding	97	1352
2421 S. New Copeland Rd.		X			1950	Domestic Single				Brick	97	1341
2503 S. New Copeland Rd.			X		1950	Domestic Single				Wood/Mixed Brick	97	1340
2510 S. New Copeland Rd.			X		1955	Domestic Single				Stucco	97	1353
2519 S. New Copeland Rd.			X		1940	Domestic Single				Stone/Wood	97	1339
2600 blk. S. New Copeland Rd.		X			1930	Domestic Single				Stucco	103	1374
2606 S. New Copeland Rd.			X		1940	Domestic Single			Tudor Revival	Red Brick	103	1371
2614 S. New Copeland Rd.			X		1935	Domestic Single			Colonial Revival	Stone	103	1372
2624 S. New Copeland Rd.		X			1935	Domestic Single				Stone	103	1373
2629 S. New Copeland Rd.		X			1950	Domestic Single				Wood	103	1369
2631 S. New Copeland Rd.			X		1940	Domestic Single			Tudor Revival	Yellow Brick	103	1370
400 blk. E. Ninth St.		X			1955	Domestic Single			Ranch	Red Brick	98	984
402 E. Ninth St.		X			1955	Domestic Single			Ranch	Yellow Brick	98	980
403 E. Ninth St.		X			1955	Domestic Single				Red Brick	98	989
408 E. Ninth St.		X			1955	Domestic Single			Ranch	Yellow Brick	98	981
409 E. Ninth St.		X			1955	Domestic Single				Brick	98	988
415 E. Ninth St.			X		1955	Domestic Single				Brick	98	987
416 E. Ninth St.		X			1955	Domestic Single			Ranch	Red Brick	98	982
422 E. Ninth St.		X			1955	Domestic Single			Ranch	Red Brick	98	983
423 E. Ninth St.		X			1955	Domestic Single				Red Brick	98	986
427 E. Ninth St.		X			1955	Domestic Single			Ranch	Yellow Brick	98	985

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference		Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		H	S	M	S	L			Roll	Frame				
200 blk.	W. Ninth St.					X		Domestic Single	Front Gabled Bungalow			Synthetic Siding	95	932
200 blk.	W. Ninth St.					X		Domestic Single	Front Gabled Bungalow			Asbestos /Wood	95	933
200 blk.	W. Ninth St.			X				Commercial	1-Part Commercial Block			Brick/Wood	95	934A
200 blk.	W. Ninth St.					X		Commercial	Lumber Yard			Wood	95	934B
700 blk.	W. Ninth St.					X		Domestic Single				Wood	94	856
723	W. Ninth St.			X				Domestic Single		Tudor Revival		Yellow Brick	94	858
725	W. Ninth St.			X				Domestic Single		Colonial Revival		Asbestos	94	857
745	W. Ninth St.					X		Domestic Single				Synthetic Siding	94	855
824	W. Ninth St.			X				Domestic Single				Red Brick	93A	753
830	W. Ninth St.					X		Domestic Single				Synthetic Siding	93A	754
900 blk.	W. Ninth St.			X				Domestic Single				Mixed Brick	93A	757
902	W. Ninth St.			X				Domestic Single				Wood	93A	755
908	W. Ninth St.					X		Domestic Single				Synthetic Siding	93A	756
920	W. Ninth St.					X		Domestic Single				Synthetic Siding	93A	758
924	W. Ninth St.			X				Domestic Single				Red Brick	93A	759
925	W. Ninth St.			X				Domestic Single				Wood	93A	752
1000 blk.	W. Ninth St.					X		Domestic Single				Yellow Brick	93A	748
1000 blk.	W. Ninth St.			X				Domestic Single				Wood	93A	749
1004	W. Ninth St.					X		Domestic Single				Wood/Yellow Brick	93A	760
1005	W. Ninth St.			X				Domestic Single				Wood	93A	751
1008	W. Ninth St.			X				Domestic Single				Wood	93A	761
1009	W. Ninth St.					X		Domestic Single				Synthetic Siding	93A	750
1014	W. Ninth St.					X		Domestic Single				Wood	93A	762
1020	W. Ninth St.					X		Domestic Single				Wood/Brick	93A	763
2420	S. Oak Ln.			X				Domestic Single				Red Brick	96	1171
2424	S. Oak Ln.					X		Domestic Single		Ranch		Red Brick	96	1172
2425	S. Oak Ln.					X		Domestic Single				Brick	96	1174
2428	S. Oak Ln.			X				Domestic Single		Colonial Revival		Red Brick	96	1173
2431	S. Oak Ln.			X				Domestic Single				Brick	96	1175
2201	S. Old Bullard Rd.					X		Commercial		Ranch		Red Brick/Wood	95	937
2202	S. Old Bullard Rd.			X				Commercial		Ranch		Brick/Wood	95	936
2211	S. Old Bullard Rd.			X				Domestic Single		Tudor Revival		Yellow Brick	96A	1269

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address	Priority	Photo Reference	Date	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
				Property Type	Subtype				
2212 S. Old Bullard Rd.	X	06 : 15	1950	Domestic Single		Ranch	Red Brick	96A	1268
2213 S. Old Bullard Rd.	X		1950	Domestic Single			Brick	96A	1270
2221 S. Old Bullard Rd.	X		1950	Domestic Single		Minimal	Red Brick	96A	1271
2224 S. Old Bullard Rd.		X	1955	Domestic Single		Ranch	Pink Brick	96A	1267
2231 S. Old Bullard Rd.		X	1955	Domestic Single		Colonial Revival	Red Brick	96A	1272
2239 S. Old Bullard Rd.	X		1940	Domestic Single		Colonial Revival	Wood	96A	1273
2306 S. Old Bullard Rd.		X	1955	Domestic Single			Red Brick	96A	1266
2310 S. Old Bullard Rd.	X		1950	Domestic Single		Colonial	Wood	96A	1265
2315 S. Old Bullard Rd.		X	1955	Domestic Single		Colonial Revival	Wood	96A	1274
2318 S. Old Bullard Rd.	X	06 : 16	1950	Domestic Single		Classical Revival	Red Brick	96A	1264
2402 S. Old Bullard Rd.	X	06 : 17	1940	Domestic Single		Colonial Revival	Brick	96A	1263
2411 S. Old Bullard Rd.	X		1950	Domestic Single		Colonial Revival	Brick	96A	1275
2417 S. Old Bullard Rd.		X	1955	Domestic Single			Red Brick	96A	1276
2424 S. Old Bullard Rd.	X	06 : 18	1940	Domestic Single		Colonial Revival	Red Brick	96A	1262A
2424 S. Old Bullard Rd. (rear)	X		1970	Domestic Auxiliary	Garage Apartment		Wood	96A	1262B
2506 S. Old Bullard Rd.	X	06 : 19	1945	Domestic Single		Colonial Revival	Brick	96A	1261
2518 S. Old Bullard Rd.	X	06 : 20	1940	Domestic Single		Colonial Revival	Brick	105	1260
2520 S. Old Bullard Rd.	X	06 : 21	1950	Domestic Single		Colonial Revival	Brick	105	1259
2601 S. Old Bullard Rd.	X	06 : 11	1950	Domestic Single		Classical Revival	Brick	105	1199
2630 S. Old Bullard Rd.	X	06 : 22	1940	Domestic Single		Tudor Revival	Yellow Brick/Stucco	105	1258
2631 S. Old Bullard Rd.	X		1950	Domestic Single		Colonial Revival	Brick	105	1198
2633 S. Old Bullard Rd.	X	06 : 12	1950	Domestic Single		Colonial Revival	Wood	105	1197
2703 S. Old Bullard Rd.		X	1955	Domestic Single		Ranch	Red Brick	105B	1239
2711 S. Old Bullard Rd.		X	1955	Domestic Single		Colonial	Pink Brick	105B	1238
2712 S. Old Bullard Rd.	X		1950	Domestic Single		Colonial Revival	Yellow Brick	105	1257
2737 S. Old Bullard Rd.	X	06 : 13	1935	Domestic Single		Tudor Revival	Pink Brick/Stucco	105B	1237
2739 S. Old Bullard Rd.	X	06 : 14	1950	Domestic Single			Red Brick	105B	1379
2747 S. Old Bullard Rd.	X		1950	Domestic Single		Colonial Revival	Yellow Brick	105B	1236
2748 S. Old Bullard Rd.		X	1955	Domestic Single		Ranch	Red Brick	105	1256
2921 S. Old Bullard Rd.	X		1940	Domestic Single		Tudor Revival	Red Brick	105B	1235
1601 S. Outer Dr.	X		1945	Domestic Single		Colonial Revival	Stone	76	712
1608 S. Outer Dr.	X		1940	Domestic Single	Front Gabled Bungalow		Stone	76	669

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Stylistic Influence	Subtype			
1609	S. Outer Dr.		X			1945	Domestic Single			Colonial Revival	Stone	76	711
1615	S. Outer Dr.			X		1950	Domestic Single				Wood	86	710
1617	S. Outer Dr.			X		1940	Domestic Single				Stone	86	709
1618	S. Outer Dr.			X		1945	Domestic Single				Synthetic Siding	86	713
1621	S. Outer Dr.			X		1955	Domestic Single				Red Brick/Wood	86	708
1624	S. Outer Dr.			X		1955	Domestic Single				Red Brick	86	714
1700 blk.	S. Outer Dr.			X		1950	Domestic Single				Wood	86	705
1700 blk.	S. Outer Dr.			X		1950	Domestic Single				Wood	86	717
1701	S. Outer Dr.			X		1940	Domestic Single				Stone	86	707
1702	S. Outer Dr.			X		1935	Domestic Single				Wood	86	715
1703	S. Outer Dr.			X		1950	Domestic Single				Wood	86	706
1704	S. Outer Dr.			X		1940	Domestic Single				Stone	86	716
1719	S. Outer Dr.			X		1950	Domestic Single				Stone	86	704
1723	S. Outer Dr.			X		1950	Domestic Single				Synthetic Siding	86	703
1727	S. Outer Dr.			X		1950	Domestic Single				Wood	86	702
521	S. Park Hgts. Ave.	X				04 : 12	Domestic Single			Tudor Revival	Red Brick	85	639
525	S. Park Hgts. Ave.	X				04 : 32	Domestic Single			Colonial Revival	Brick	94	875
529	S. Park Hgts. Ave.	X				04 : 31	Domestic Single			Monterey	Red Brick	94	876
530	S. Park Hgts. Ave.		X			1945	Domestic Single			Colonial Revival	Red Brick	94	886
535	S. Park Hgts. Ave.		X			1955	Domestic Single			Ranch	Brick	94	877
536	S. Park Hgts. Ave.		X			04 : 33	Domestic Single			Colonial Revival	Brick	94	885
538	S. Park Hgts. Ave.		X			1945	Domestic Single			Colonial Revival	Red Brick	94	884
543	S. Park Hgts. Ave.	X				04 : 30	Domestic Single			Tudor Revival	Stone	94	878
545	S. Park Hgts. Ave.		X			1955	Domestic Single			Colonial Revival	Pink Brick	94	879
546	S. Park Hgts. Ave.		X			1950	Domestic Single			Colonial Revival	Brick	94	883
550	S. Park Hgts. Ave.		X			1955	Domestic Single			Colonial Revival	Mixed Brick	94	882
551	S. Park Hgts. Ave.		X			1950	Domestic Single			Colonial Revival	Red Brick	94	880
553	S. Park Hgts. Ave.		X			1955	Domestic Single			Colonial Revival	Red Brick	94	881
627	E. Rhodes		X			1950	Domestic Single				Wood	103	1365
633	E. Rhodes		X			1950	Domestic Single				Synthetic Siding	103	1366
700 blk.	E. Rhodes		X			1955	Domestic Single				Synthetic Siding	103	1368
701	E. Rhodes		X			1950	Domestic Single				Vinyl Siding	103	1367

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority				Photo Reference		Date	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M	SL	Roll	Frame		Slide	Property Type	Subtype			
1708	S. Robertson Ave.				X			1940	Domestic Single			Wood	85	648
1806	S. Robertson Ave.				X			1925	Domestic Single	Front Gabled Bungalow		Wood	85	649
1814	S. Robertson Ave.				X			1950	Domestic Single			Yellow Brick	94	900
1815	S. Robertson Ave.			X				1935	Domestic Single		Tudor Revival	Brick	94	899
1818	S. Robertson Ave.				X			1955	Domestic Single			Red Brick	94	901
1901	S. Robertson Ave.		X			04 : 19		1940	Domestic Single		Colonial Revival	Red Brick	94	898
1903	S. Robertson Ave.			X				1935	Domestic Single		Classical Revival	Brick	94	897
1907	S. Robertson Ave.			X				1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	94	896
1912	S. Robertson Ave.			X				1945	Domestic Single			Brick	94	902
1920	S. Robertson Ave.			X				1945	Domestic Single			Brick/Wood	94	903A
1920	S. Robertson Ave. (rear)			X				1950	Domestic Auxiliary	Garage Apartment		Wood	94	903B
2000 blk.	S. Robertson Ave.				X			1940	Domestic Single			Synthetic Siding	94	907
2002	S. Robertson Ave.			X				1940	Domestic Single		Colonial Revival	Brick	94	904
2003	S. Robertson Ave.			X				1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	94	895
2005	S. Robertson Ave.			X				1935	Domestic Single	Cross Gabled Bungalow		Brick	94	894
2010	S. Robertson Ave.			X				1940	Domestic Single		Colonial Revival	Brick/Wood	94	905
2018	S. Robertson Ave.			X				1940	Domestic Single		Colonial Revival	Brick	94	906
2023	S. Robertson Ave.			X				1950	Domestic Single			Brick	94	893
2100 blk.	S. Robertson Ave.	X				04 : 17		1935	Domestic Single		Tudor Revival	Red Brick	94	892A
2100 blk.	S. Robertson Ave. (rear)		X			04 : 18		1935	Domestic Auxiliary	Garage Apartment	Tudor Revival	Red Brick	94	892B
2201	S. Robertson Ave.	X				04 : 16		1915	Domestic Single		Classical Revival	Wood	94	891
2205	S. Robertson Ave.	X						1935	Domestic Single		Tudor Revival	Red Brick	96	1165
2300 blk.	S. Robertson Ave.			X				1955	Infrastructure and Utilities	Electric Generating		Red Brick	96	1166
2314	S. Robertson Ave.			X				1950	Domestic Single		Ranch	Red Brick	96	1167
2400	S. Robertson Ave.			X				1950	Domestic Single			Brick	96	1168
2400 blk.	S. Robertson Ave.			X				1950	Domestic Single			Brick	93B	826
2403	S. Robertson Ave.			X				1950	Domestic Single			Asbestos	96	1164
2404	S. Robertson Ave.			X				1950	Domestic Single			Pink Brick	96	1169
2408	S. Robertson Ave.			X				1940	Domestic Single			Yellow Brick	96	1170
2409	S. Robertson Ave.				X			1955	Domestic Single		Ranch	Red Brick	96	1163
2429	S. Robertson Ave.			X				1940	Domestic Single		Colonial Revival	Synthetic Siding	93B	825
412	W. Rose Circle				X			1955	Domestic Single		Colonial Revival	Red Brick	105B	1234

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address	Priority	Photo Reference	Date	Property Type	Identification Subtype	Stylistic Influence	Exterior Materials	Mcp No.	I.D. No.
Street Number and Name	H S M L SL	Roll :Frame Slide							
414 W. Rose Circle	X		1955	Domestic Single		Colonial Revival	Brick	1058	1233
417 W. Rose Circle		X	1955	Domestic Single		Colonial Revival	Pink Brick	1058	1232
1302 S. Roseland Blvd.	X		1945	Domestic Single			Yellow Brick	79	245
1310 S. Roseland Blvd.	X		1940	Domestic Single			Brick/Wood	79	246
1326 S. Roseland Blvd.	X	02:22	1940	Domestic Single		Colonial Revival	Pink Brick	79	247A
1326 S. Roseland Blvd. (rear)	X		1940	Domestic Single		Colonial Revival	Pink Brick	79	247B
1408 S. Roseland Blvd.	X	02:23	1935	Domestic Single		Colonial Revival	Brick	79	248
100 -300blk. W. Rusk St.	X	01:20	1925	Infrastructure and Utilities	Street		Red Brick	70	74
200 blk. W. Rusk St.	X	01:01	1940	Religious	Church		Red Brick	70	1
302 -04 W. Rusk St.		X	1940	Commercial	1-Part Commercial Block		Brick	70	2
314 W. Rusk St.	X	01:02	1935	Commercial	1-Part Commercial Block	Art Deco	Brick	70	3
318 W. Rusk St.	X		1915	Domestic Single	Side Gabled Bungalow		Wood	70	4
403 E. Seagle St.		X	1955	Domestic Single			Wood	97	1293
407 E. Seagle St.		X	1945	Domestic Single			Red Brick/Wood	97	1292
427 E. Seagle St.	X		1940	Domestic Single		Ranch /Tudor	Brick	97	1291
600 blk. E. Seagle St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	97	1294
100 blk. E. Second St.	X	02:16	1940	Religious	Church	Classical Revival	Red Brick	79	217
105 E. Second St.	X	02:15	1945	Domestic Single		Ranch	Brick	79	216
114 E. Second St.	X		1935	Domestic Single		Colonial Revival	Red Brick/Wood	79	218
115 E. Second St.	X	02:20	1935	Domestic Single		Colonial Revival	Brick	79	215
118 E. Second St.	X	02:17	1935	Domestic Single		Monterey	Brick	79	219
123 E. Second St.	X	02:19	1935	Domestic Single		Colonial	Brick	79	214
213 E. Second St.	X	02:18	1935	Domestic Single		Colonial Revival	Brick	79	213
223 E. Second St.	X		1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	79	212
305 E. Second St.	X	02:24	1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	211
308 E. Second St.	X		1940	Domestic Single		Colonial Revival	Mixed Brick/Wood	79	220
313 E. Second St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	210
400 blk. E. Second St.		X	1955	Domestic Single			Wood	80	293
411 E. Second St.	X		1940	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Red Brick	80	262
414 E. Second St.	X		1955	Domestic Single		Ranch	Pink Brick	80	264
415 E. Second St.	X		1950	Domestic Single		Ranch	Mixed Brick	80	263
512 E. Second St.	X		1950	Domestic Single		Ranch	Brick	80	265

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority			Photo Reference		Date	Identification		Exterior Materials		Map No.	I.D. No.
Street Number and Name	H	S	M	L	Rel	Frame Slide	Date	Property Type	Subtype	Stylistic Influence	Materials	Map No.	I.D. No.
515 E. Second St.		X					1935	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Brick	80	266
519 E. Second St.			X				1940	Domestic Single		Colonial Revival	Brick/Wood	80	267
521 E. Second St.						X	1940	Domestic Single		Colonial Revival	Brick	80	268
600 blk. E. Second St.		X					1940	Infrastructure and Utilities	Bridge		Concrete	80	270A
600 blk. E. Second St.			X				1940	Infrastructure and Utilities	Bridge		Concrete	80	270B
603 E. Second St.				X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	80	274
609 E. Second St.				X			1935	Domestic Single		Colonial Revival	Brick	80	273
611 E. Second St.				X			1935	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Brick	80	272
612 E. Second St.				X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Red Brick	80	269
100 blk. W. Second St.				X			1935	Domestic Single		Tudor Revival	Brick	79	129
215 W. Second St.		X				01 : 32	1935	Domestic Single		Tudor Revival	Brick	79	128A
215 W. Second St. (rear)			X				1935	Domestic Auxiliary	Garage Apartment		Brick	79	128B
308 W. Second St.				X			1935	Domestic Auxiliary	Garage Apartment		Yellow Brick	79	130B
314 W. Second St.				X			1935	Domestic Single	Cross Gabled Bungalow		Brick	79	131A
314 W. Second St. (rear)				X			1935	Domestic Auxiliary	Garage Apartment		Wood	79	131B
316 W. Second St.			X				1940	Domestic Single		Colonial Revival	Brick	79	132
319 W. Second St.				X			1935	Domestic Single			Brick	79	127A
319 W. Second St. (rear)				X			1935	Domestic Auxiliary	Garage Apartment		Wood	79	127B
323 W. Second St.			X				1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	126
807 W. Seventh Ave.				X			1950	Domestic Single			Synthetic Siding	93A	735
811 W. Seventh Ave.						X	1940	Domestic Single			Synthetic Siding	93A	734
815 W. Seventh Ave.						X	1950	Domestic Single			Synthetic Siding	93A	733
823 W. Seventh Ave.						X	1935	Domestic Single	Cross Gabled Bungalow		Synthetic Siding	93A	732
827 W. Seventh Ave.						X	1950	Domestic Single			Synthetic Siding	93A	731
829 -31 W. Seventh Ave.						X	1950	Domestic Single			Red Brick	93A	730
900 blk. W. Seventh Ave.						X	1940	Domestic Single			Synthetic Siding	93A	728
915 W. Seventh Ave.						X	1945	Domestic Single			Wood	93A	729
921 W. Seventh Ave.				X			1950	Domestic Single			Wood	93A	727
924 W. Seventh Ave.				X			1950	Domestic Single			Asbestos	93A	736
1004 W. Seventh Ave.						X	1950	Domestic Single			Synthetic Siding	93A	737
1005 W. Seventh Ave.						X	1950	Domestic Single			Synthetic Siding	93A	726
1008 W. Seventh Ave.				X			1950	Domestic Single			Synthetic Siding	93A	738

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority HSM/MS/L	Photo Reference Roll:Frame Slide	Date	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
					Property Type	Subtype				
1009	W. Seventh Ave.	X		1940	Domestic Single	Side Gabled Bungalow	Classical Revival	Brick	93A	725
1013	W. Seventh Ave.		X	1940	Domestic Single	Front Gabled Bungalow		Synthetic Siding	93A	724
118	W. Seventh St.	X		1940	Domestic Single			Red Brick	95	922
125	W. Seventh St.	X		1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	84	509
202	W. Seventh St.		X	1950	Domestic Single			Brick	95	921
209	W. Seventh St.	X		1940	Domestic Single			Brick	84	510
210	W. Seventh St.	X		1950	Domestic Single			Brick	95	920
310	W. Seventh St.	X	04:34	1935	Domestic Single			Red Brick	95	919A
310	W. Seventh St. (rear)	X		1950	Domestic Auxillary	Garage Apartment	Colonial Revival	Wood	95	919B
320	W. Seventh St.	X	04:35	1935	Domestic Single			Brick	95	918
400	W. Seventh St.	X	05:01	1950	Domestic Single			Red Brick	95	917
401	W. Seventh St.	X	03:23	1955	Domestic Single			Yellow Brick	84	1378
406	W. Seventh St.	X	05:02	1950	Domestic Single			Red Brick	95	916
407	W. Seventh St.	X	03:22	1935	Domestic Single		Colonial Revival	Brick	84	511
100 -200blk.	W. Shaw St.	X	02:13	1935	Infrastructure and Utilities	Street		Red Brick	79	250
108	W. Shaw St.	X		1930	Domestic Auxillary	Garage Apartment		Red Brick	79	75
114	W. Shaw St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	76
115	W. Shaw St.	X		1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Wood	70	37
118	W. Shaw St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	77A
118	W. Shaw St. (rear)	X		1940	Domestic Auxillary	Garage Apartment		Wood	79	77B
119	W. Shaw St.		X	1930	Domestic Single	Side Gabled Bungalow		Brick	70	36
200 blk.	W. Shaw St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	78A
200 blk.	W. Shaw St.	X		1935	Domestic Auxillary			Wood	79	78B
201	W. Shaw St.	X		1920	Domestic Single			Wood	70	35
205	W. Shaw St.		X	1925	Domestic Single	Cross Gabled Bungalow		Synthetic Siding	70	34
206	W. Shaw St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	79	79
211	W. Shaw St.	X		1930	Domestic Single	Side Gabled Bungalow	Craftsman	Wood	70	33
215	W. Shaw St.	X		1925	Domestic Single	Cross Gabled Bungalow	Craftsman	Wood	70	32
221	W. Shaw St.	X		1925	Domestic Single			Asbestos	70	31
309	W. Shaw St.	X		1935	Domestic Auxillary	Garage Apartment	Colonial Revival	Brick	70	30
310	W. Shaw St.	X		1935	Domestic Auxillary	Garage Apartment	Tudor Revival	Red Brick	79	80
312	W. Shaw St.	X		1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Wood	79	81A

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
	H	S	M				Subtype					
312 W. Shaw St. (rear)		X			1940	Domestic Auxiliary	Garage Apartment		Wood	79	81B	
313 W. Shaw St.				X	1925	Domestic Single			Red Brick	70	29	
318 W. Shaw St.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Wood	79	82A	
318 1/2 W. Shaw St.		X			1945	Domestic Auxiliary	Garage Apartment		Wood	79	82B	
323 W. Shaw St.		X			1910	Domestic Single	Massed Plan Pyramidal	Classical Revival	Wood	70	28	
326 W. Shaw St.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Synthetic Sliding	79	83	
402 W. Shaw St.		X			1930	Domestic Single	Cross Gabled Bungalow	Craftsman	Wood	79	84	
404 W. Shaw St.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	79	85	
406 W. Shaw St.			X		1935	Domestic Single		Tudor Revival	Brick/Stone	79	86	
401 E. Sixth St.		X			1945	Domestic Multiple	Duplex	Ranch	Red Brick	98	946	
407 E. Sixth St.		X			1945	Domestic Multiple	Duplex		Yellow Brick	98	947	
409 E. Sixth St.		X			1945	Domestic Multiple	Duplex		Yellow Brick	98	948	
410 E. Sixth St.			X		1940	Domestic Single		Colonial Revival	Brick	83A	428	
412 E. Sixth St.		X			1945	Domestic Single			Brick	83A	429	
413 -15 E. Sixth St.		X			1945	Domestic Multiple	Duplex		Yellow Brick	98	949	
417 -19 E. Sixth St.		X			1945	Domestic Multiple	Duplex		Red Brick	98	950	
422 E. Sixth St.			X		1950	Domestic Single			Brick	83A	430	
423 -25 E. Sixth St.		X			1945	Domestic Multiple	Duplex		Brick	98	951	
504 E. Sixth St.		X			1915	Domestic Single			Asbestos	83A	431	
510 E. Sixth St.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	83A	432	
511 E. Sixth St.		X			1950	Domestic Single		Ranch	Red Brick	98	952	
100 blk. W. Sixth St.		X			1930	Commercial	1-Part Commercial Block		Wood/Brick	84	501	
108 W. Sixth St.		X			1940	Domestic Single	Cross Gabled Bungalow		Yellow Brick	84	502	
114 W. Sixth St.		X			1935	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Yellow Brick	84	503	
300 blk. W. Sixth St.		X			1935	Domestic Single		Italian	Stone	84	504	
321 W. Sixth St.		X			1950	Domestic Single		Colonial Revival	Red Brick	84	508	
401 W. Sixth St.		X			1935	Domestic Single		Classical Revival	Brick	84	507	
404 W. Sixth St.		X			1935	Domestic Single		Italian	Stone	84	505	
407 W. Sixth St.		X			1950	Domestic Single			Stone	84	506	
500 blk. W. Sixth St.		X			1940	Domestic Single	Front Gabled Bungalow	Tudor Revival	Brick	85	593	
508 W. Sixth St.		X			1940	Domestic Single		Colonial Revival	Brick	85	590	
509 W. Sixth St.			X		1930	Domestic Single	Cross Gabled Bungalow		Asbestos	85	638	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Stylistic Influence				
514	W. Sixth St.	X				1935	Domestic Single			Tudor Revival	Brick/Wood	85	591
518	W. Sixth St.		X			1935	Domestic Single			Colonial Revival	Red Brick/Wood	85	592
525	W. Sixth St.			X		1925	Domestic Single				Brick	85	637
527	W. Sixth St.		X			1940	Domestic Single			Colonial Revival	Yellow Brick	85	636
528	W. Sixth St.		X			1935	Domestic Single			Tudor Revival	Brick	85	594
530	W. Sixth St.		X			1935	Domestic Single			Cross Gabled Bungalow	Yellow Brick	85	595
531	W. Sixth St.		X			1935	Domestic Single			Cross Gabled Bungalow	Yellow Brick	85	635
538	W. Sixth St.		X			1935	Domestic Single			Cross Gabled Bungalow	Brick	85	596
600 blk.	W. Sixth St.			X		1940	Religious			Church	Yellow Brick	85	540
600 blk.	W. Sixth St.		X			1940	Domestic Single			Colonial Revival	Brick	85	597
611	W. Sixth St.		X			1925	Domestic Single			Front Gabled Bungalow	Wood	85	634
615	W. Sixth St.			X		1940	Domestic Single			Front Gabled Bungalow	Wood	85	633
621	W. Sixth St.		X			1945	Domestic Single			Colonial Revival	Brick	85	632
704	W. Sixth St.		X			1940	Domestic Single				Synthetic Siding	85	598
705	W. Sixth St.			X		1950	Domestic Single			Ranch	Brick	85	631
710	W. Sixth St.		X			1945	Domestic Single				Mixed Brick/Wood	85	599
711	W. Sixth St.		X			1950	Domestic Single			Colonial Revival	Brick	85	630
716	W. Sixth St.		X			1940	Domestic Single				Brick	85	600
717	W. Sixth St.		X			1950	Domestic Single			Colonial Revival	Red Brick	85	629
722	W. Sixth St.		X			1940	Domestic Single			Colonial Revival	Yellow Brick	85	601
800 blk.	W. Sixth St.			X		1950	Domestic Single				Synthetic Siding	85	607
800 blk.	W. Sixth St.		X			1950	Domestic Single			Ranch	Yellow Brick	85	624
801	W. Sixth St.			X		1945	Domestic Single			Colonial Revival	Brick	85	628
804	W. Sixth St.		X			1940	Domestic Single			Colonial Revival	Red Brick	85	602
805	W. Sixth St.		X			1950	Domestic Single			Ranch	Brick	85	627
810	W. Sixth St.			X		1940	Domestic Single			Colonial Revival	Brick	85	603
811	W. Sixth St.			X		1950	Domestic Single			Ranch	Red Brick	85	626
812	W. Sixth St.		X			1950	Domestic Single			Ranch	Red Brick/Wood	85	604
815	W. Sixth St.		X			1950	Domestic Single			Ranch	Yellow Brick	85	625
816	W. Sixth St.			X		1950	Domestic Single			Ranch	Brick	85	605
822	W. Sixth St.		X			1950	Domestic Single			Ranch	Yellow Brick	85	606
825	W. Sixth St.			X		1950	Domestic Single			Ranch	Brick	85	623

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Priority			Photo Reference Roll #frame Slide	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
	H	S	M				Subtype	Subtype				
900 blk. W. Sixth St.		X			1950	Domestic Single			Ranch	Wood	85	612
903 W. Sixth St.			X		1950	Domestic Single			Ranch	Brick/Wood	85	622
904 W. Sixth St.		X			1945	Domestic Single				Wood	85	608
905 W. Sixth St.			X		1950	Domestic Single			Ranch	Synthetic Siding	85	621
908 W. Sixth St.		X			1945	Domestic Single	Side Gabled Bungalow		Colonial Revival	Asbestos	85	609
913 W. Sixth St.		X			1950	Domestic Single			Ranch	Brick/Asbestos	85	620
914 W. Sixth St.			X		1950	Domestic Single			Ranch	Synthetic Siding	85	610
919 W. Sixth St.		X			1945	Domestic Single			Ranch	Yellow Brick	85	619
920 W. Sixth St.		X			1950	Domestic Single			Ranch	Synthetic Siding	85	611
923 W. Sixth St.			X		1945	Domestic Single			Ranch	Yellow Brick/Asbestos	85	618
927 W. Sixth St.			X		1950	Domestic Single			Ranch	Brick	85	617
1004 W. Sixth St.			X		1950	Domestic Single			Ranch	Red Brick	85	613
1005 W. Sixth St.				X	1945	Domestic Single			Ranch	Pink Brick	85	616
1010 W. Sixth St.		X			1950	Domestic Single			Ranch	Red Brick	85	614
1011 W. Sixth St.			X		1950	Domestic Single			Ranch	Brick	85	615
1100 blk. W. Sixth St.			X		1930	Domestic Single				Red Brick/Wood	86	685
1100 blk. W. Sixth St.			X		1950	Domestic Single				Yellow Brick/Wood	86	687
1118 W. Sixth St.			X		1950	Domestic Single			Ranch	Red Brick	86	686
1200 W. Sixth St.			X		1950	Domestic Single				Wood/Red Brick	86	688
1200 blk. W. Sixth St.			X		1950	Domestic Auxiliary	Garage Apartment			Wood	86	691
1203 W. Sixth St.		X			1950	Domestic Single				Wood/Mixed Brick	86	684
1204 W. Sixth St.		X			1950	Domestic Single				Synthetic Siding	86	689
1209 W. Sixth St.		X			1950	Domestic Single				Yellow Brick	86	683
1210 W. Sixth St.			X		1950	Domestic Single				Wood	86	690
1214 W. Sixth St.			X		1940	Domestic Single				Asbestos	86	692
1225 W. Sixth St.			X		1950	Domestic Single				Stone	86	682
1300 blk. W. Sixth St.			X		1950	Domestic Single				Wood	86	699A
1300 blk. W. Sixth St. (rear)			X		1950	Domestic Auxiliary	Garage Apartment			Wood	86	699B
1309 W. Sixth St.			X		1950	Domestic Single				Wood	86	701
1315 W. Sixth St.			X		1950	Domestic Single				Synthetic Siding	86	700
1322 W. Sixth St.		X			1950	Domestic Single				Wood	86	693
1400 blk. W. Sixth St.			X		1955	Domestic Single				Red Brick	86	695

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority H S M L	Photo Reference L Roll :Frame Slide	Date	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
					Property Type	Subtype				
1400 blk.	W. Sixth St.		X	1950	Domestic Single			Synthetic Siding	86	698
1402	W. Sixth St.		X	1955	Domestic Single			Synthetic Siding	86	694
1403	W. Sixth St.		X	1950	Domestic Single			Synthetic Siding	86	697
1410	W. Sixth St.		X	1955	Domestic Single		Ranch	Red Brick	86	696
1124	S. Sneed Ave.		X	1935	Domestic Single		Tudor Revival	Red Brick/Asbestos	80	375
1201	S. Sneed Ave.		X	1935	Domestic Single		Minimal	Brick	80	374A
1201	S. Sneed Ave. (rear)		X	1950	Domestic Auxiliary			Wood/Vinyl Siding	80	374B
1203	S. Sneed Ave.		X	1935	Domestic Single		Side Gabled Bungalow	Yellow Brick	80	373
1204	S. Sneed Ave.		X	1940	Domestic Single			Stone/Vinyl Siding	80	376
1208	S. Sneed Ave.		X	1940	Domestic Single			Brick	80	377
1211	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	372
1215	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	371
1221	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	370
1222	S. Sneed Ave.		X	1935	Domestic Single			Brick	80	378
1300 blk.	S. Sneed Ave.		X	1935	Domestic Single			Brick	80	363
1300 blk.	S. Sneed Ave.		X	1935	Domestic Single			Brick	80	369
1302	S. Sneed Ave.		X	1935	Domestic Single			Red Brick	80	379
1303	S. Sneed Ave.		X	1935	Domestic Single			Brick	80	368
1310	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	380
1311	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	367
1317	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	366
1321	S. Sneed Ave.		X	1935	Domestic Single			Yellow Brick	80	365
1323	S. Sneed Ave.		X	1935	Domestic Single			Brick	80	364
1402	S. Sneed Ave.		X	1935	Domestic Single			Brick	80	381
1403	S. Sneed Ave.		X	1935	Domestic Single			Red Brick	80	362
1412	S. Sneed Ave.		X	1940	Domestic Single			Pink Brick	80	382
1521	S. Sneed Ave.		X	1955	Domestic Single		Ranch	Red Brick/Wood	80	361A
1521	S. Sneed Ave. (rear)		X	1955	Domestic Auxiliary		Garage Apartment	Wood	80	361B
1620	S. Sneed Ave.		X	1940	Domestic Single			Wood	83A	457
1703	S. Sneed Ave.		X	1940	Domestic Single			Brick	83A	458
1708	S. Sneed Ave.		X	1950	Domestic Single			Red Brick	83A	454
1805	S. Sneed Ave.		X	1945	Domestic Single			Red Brick	83A	453

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference		Date	Property Type	Identification			Exterior Materials	Mcp No.	I.D. No.
		H	S	M	S	L			Roll	Frame	Slide			
1826	S. Sneed Ave.				X		1955	Domestic Single		Ranch	Yellow Brick	98	1013	
1900	S. Sneed Ave.				X		1955	Domestic Single		Ranch	Brick	98	1014	
1900 blk.	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Red Brick	98	1032	
1900 blk.	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Red Brick	98	1035	
1901	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Red Brick	98	1036	
1912	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Synthetic Siding	98	1015	
1913	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Red Brick	98	1034	
1916	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Pink Brick	98	1016	
1919	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Red Brick	98	1033	
1922	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Synthetic Siding	98	1017	
1929	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Red Brick	98	1031	
2000	S. Sneed Ave.			X			1955	Domestic Single		Ranch	Wood/Brick	98	1018	
2007	S. Sneed Ave.			X			1950	Domestic Single		Colonial Revival	Red Brick	98	1030	
2015	S. Sneed Ave.			X			1945	Domestic Single			Yellow Brick	98	1029	
2016	S. Sneed Ave.			X			1940	Domestic Single			Yellow Brick	98	1019	
2021	S. Sneed Ave.			X			1940	Domestic Single			Yellow Brick	98	1028	
2024	S. Sneed Ave.			X			1950	Domestic Single			Red Brick	98	1020	
2025	S. Sneed Ave.			X			1940	Domestic Single			Brick	98	1027	
2100	S. Sneed Ave.			X			1950	Domestic Single			Red Brick	98	1021	
2103	S. Sneed Ave.			X			1940	Domestic Single		Tudor Revival	Brick	98	1026	
2106	S. Sneed Ave.			X			1950	Domestic Single			Synthetic Siding	98	1022	
2109	S. Sneed Ave.			X			1950	Domestic Single		Ranch	Red Brick	98	1025	
2112	S. Sneed Ave.			X			1950	Domestic Single			Yellow Brick	98	1023	
2118	S. Sneed Ave.			X			1950	Domestic Single		Colonial Revival	Yellow Brick	98	1024	
2000 blk.	S. Sunnysbrook Dr.	X				04 : 14	1950	Infrastructure and Utilities	Headwall		Concrete	93A	802	
2000 blk.	S. Sunnysbrook Dr.	X				04 : 15	1950	Infrastructure and Utilities	Drainage Channel		Concrete	93A	803	
2002	S. Sunnysbrook Dr.			X			1950	Domestic Single			Synthetic Siding	93A	801	
2008	S. Sunnysbrook Dr.			X			1950	Domestic Single			Brick	93A	800	
2014	S. Sunnysbrook Dr.			X			1950	Domestic Single			Synthetic Siding	93A	799	
2020	S. Sunnysbrook Dr.			X			1950	Domestic Single			Synthetic Siding	93A	798	
2100 blk.	S. Sunnysbrook Dr.			X			1950	Domestic Single			Wood	93A	797	
2108	S. Sunnysbrook Dr.			X			1950	Domestic Single			Wood	93A	796	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Stylistic Influence				
2116	S. Sunnybrook Dr.			X		1945	Domestic Single			Wood	93A	795	
2122	S. Sunnybrook Dr.		X			1945	Domestic Single			Wood	93A	794	
2300 blk.	S. Sunnybrook Dr.		X			1950	Infrastructure and Utilities	Headwall		Concrete	93B	816	
2308	S. Sunnybrook Dr.			X		1955	Domestic Single			Yellow Brick	93B	838	
2320	S. Sunnybrook Dr.			X		1955	Domestic Single			Stone	93B	837	
2400 blk.	S. Sunnybrook Dr.		X			1950	Infrastructure and Utilities	Headwall		Concrete	93B	817	
2400 blk.	S. Sunnybrook Dr.			X		1950	Domestic Single			Synthetic Siding	93B	827	
2422	S. Sunnybrook Dr.			X		1955	Domestic Single			Brick	93B	836	
2438	S. Sunnybrook Dr.		X			1950	Domestic Single			Wood/Brick	93B	828	
2500 blk.	S. Sunnybrook Dr.		X			1950	Infrastructure and Utilities	Headwall		Concrete	93B	824	
2506 -04	S. Sunnybrook Dr.			X		1950	Domestic Multiple	Duplex		Wood	96	1162	
2512	S. Sunnybrook Dr.			X		1955	Domestic Single			Yellow Brick	96	1161	
2518	S. Sunnybrook Dr.			X		1955	Domestic Single			Mixed Brick	96	1160	
2524	S. Sunnybrook Dr.			X		1950	Domestic Single			Yellow Brick	96	1159	
2530	S. Sunnybrook Dr.			X		1950	Domestic Single			Red Brick	96	1158	
2534	S. Sunnybrook Dr.			X		1950	Domestic Single			Yellow Brick	96	1157	
2618	S. Sunnybrook Dr.			X		1950	Domestic Single			Yellow Brick	105	1195	
2708	S. Sunnybrook Dr.			X		1955	Domestic Single			Mixed Brick	105A	1215	
2714	S. Sunnybrook Dr.			X		1955	Domestic Single			Mixed Brick	105A	1214	
2720	S. Sunnybrook Dr.			X		1950	Domestic Single			Brick	105A	1213	
2726	S. Sunnybrook Dr.			X		1950	Domestic Single			Mixed Brick	105A	1212	
2800	S. Sunnybrook Dr.			X		1950	Domestic Single			Red Brick	105A	1211	
2810	S. Sunnybrook Dr.			X		1950	Domestic Single			Red Brick	105A	1210	
2900	S. Sunnybrook Dr.			X		1955	Domestic Single			Brick/Vinyl Siding	105A	1209	
2912	S. Sunnybrook Dr.			X		1955	Domestic Single			Mixed Brick	105A	1208	
2918	S. Sunnybrook Dr.			X	06 : 09	1950	Domestic Single			Red Brick	105A	1207	
2924	S. Sunnybrook Dr.			X		1955	Domestic Single			Mixed Brick	105A	1206	
1900 blk.	S. Talley Ave.			X		1950	Domestic Single			Synthetic Siding	93A	788	
1903	S. Talley Ave.			X		1950	Domestic Single			Synthetic Siding	93A	790	
1909	S. Talley Ave.			X		1940	Domestic Single			Wood	93A	789	
1919	S. Talley Ave.			X		1950	Domestic Single			Stone	93A	787	
2000 blk.	S. Talley Ave.			X		1950	Domestic Single			Wood/Asbestos	93A	785	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Address		Priority					Photo Reference		Date	Identification			Exterior Materials	Map No.	I.D. No.	
Street Number and Name		H	S	M	S	L	Roll	Frame		Slide	Property Type	Subtype				Stylistic Influence
2005	S. Talley Ave.					X				1950	Domestic Single			Wood/Red Brick	93A	786
2019	S. Talley Ave.					X				1950	Domestic Single			Synthetic Siding	93A	784
829	W.Tenth St.			X						1950	Domestic Single			Wood	93A	782
900	W.Tenth St.					X				1945	Domestic Single			Asbestos	93A	764
900 blk.	W.Tenth St.					X				1950	Domestic Single			Synthetic Siding	93A	767
900 blk.	W.Tenth St.			X						1950	Domestic Single		Colonial Revival	Wood	93A	779
903	W.Tenth St.			X						1950	Domestic Single			Wood	93A	781
908	W.Tenth St.					X				1945	Domestic Single			Synthetic Siding	93A	765
909	W.Tenth St.			X						1950	Domestic Single		Ranch	Synthetic Siding	93A	780
914	W.Tenth St.			X						1950	Domestic Single			Synthetic Siding	93A	766
919	W.Tenth St.					X				1950	Domestic Single		Ranch	Wood	93A	778
925	W.Tenth St.					X				1950	Domestic Single			Yellow Brick	93A	777
926	W.Tenth St.					X				1950	Domestic Single			Wood	93A	768
1000 blk.	W.Tenth St.					X				1950	Domestic Single			Wood	93A	770
1004	W.Tenth St.			X						1945	Domestic Single		Colonial Revival	Wood	93A	769
1005	W.Tenth St.					X				1950	Domestic Single			Red Brick	93A	776
1009	W.Tenth St.			X						1950	Domestic Single			Wood	93A	775
1013	W.Tenth St.					X				1950	Domestic Single			Wood	93A	774
1020	W.Tenth St.					X				1950	Domestic Single			Synthetic Siding	93A	771
1021	W.Tenth St.			X						1945	Domestic Single			Yellow Brick	93A	773
1024	W.Tenth St.			X						1950	Domestic Single			Wood	93A	772
102	E. Third St.			X						1940	Domestic Single		Colonial Revival	Brick	79	221
103	E. Third St.			X						1955	Domestic Single		Ranch	Red Brick	84	465
108	E. Third St.			X						1940	Domestic Single		Colonial Revival	Yellow Brick	79	222
111	E. Third St.			X						1955	Domestic Single		Ranch	Red Brick	84	464
114	E. Third St.			X						1940	Domestic Single		Colonial Revival	Red Brick	79	223
117	E. Third St.			X						1940	Domestic Single		Colonial Revival	Red Brick	84	463
118	E. Third St.			X						1940	Domestic Single		Colonial Revival	Yellow Brick	79	224
206	E. Third St.		X				02	:21		1940	Domestic Single		Colonial Revival	Stone	79	225
209	E. Third St.	X					03	:06		1940	Domestic Single	Garage Apartment	Chateausque	Stone	84	462A
209	E. Third St. (rear)		X				03	:07		1940	Domestic Auxilliary		Chateausque	Stone	84	462B
222	E. Third St.			X						1940	Domestic Single		Colonial Revival	Red Brick	79	226

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Priority		Photo Reference Roll: Frame Slide	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
	H	M/S/L				Subtype					
223 E. Third St.	X		03 : 05	1940	Domestic Single			Colonial Revival	Red Brick/Synthetic	84	461
300 E. Third St.		X		1940	Domestic Single			Colonial Revival	Yellow Brick	79	227
301 E. Third St.	X		03 : 04	1940	Domestic Single			Monterey	Brick/Vinyl Siding	84	460
308 E. Third St.		X		1945	Domestic Single			Colonial Revival	Yellow Brick	79	228
311 E. Third St.		X		1945	Domestic Single				Brick	84	459
400 blk. E. Third St.		X		1940	Domestic Single			Colonial Revival	Yellow Brick	80	291
401 E. Third St.		X		1935	Domestic Single			Colonial Revival	Brick	80	292
403 E. Third St.		X		1940	Domestic Single			Colonial Revival	Brick	80	275
408 E. Third St.			X	1935	Domestic Single			Colonial Revival	Brick/Vinyl Siding	80	276
410 E. Third St.		X		1940	Domestic Single				Brick	80	277
414 E. Third St.		X		1955	Domestic Single			International	Pink Brick	80	278
512 E. Third St.		X		1950	Domestic Single			Colonial Revival	Red Brick	80	279
513 E. Third St.		X		1940	Domestic Single			Colonial Revival	Red Brick	80	290
517 E. Third St.		X		1940	Domestic Single			Colonial Revival	Yellow Brick	80	289
520 E. Third St.		X		1950	Domestic Single			Colonial Revival	Brick	80	280A
520 blk. E. Third St.		X		1950	Domestic Single				Wood	80	280B
602 E. Third St.		X		1940	Infrastructure and Utilities	Bridge			Concrete	80	285
603 E. Third St.		X		1935	Domestic Single			Colonial Revival	Brick/Wood	80	281
607 E. Third St.		X		1935	Domestic Single			Tudor Revival	Brick	80	288
610 E. Third St.		X		1940	Domestic Single			Tudor Revival	Brick	80	287
614 E. Third St.		X		1950	Domestic Single			Colonial Revival	Red Brick/Wood	80	282
615 E. Third St.		X		1940	Domestic Single			Colonial Revival	Brick	80	283
703 E. Third St.		X		1955	Domestic Single			Colonial Revival	Red Brick/Wood	80	286
300 blk. W. Third St.		X	02 : 04	1935	Domestic Multiple			Ranch	Red Brick	80	284
314 W. Third St.		X	03 : 10	1935	Domestic Single			Tudor Revival	Brick	79	135
318 W. Third St.		X		1935	Domestic Single			Tudor Revival	Yellow Brick	84	480
321 - 17 W. Third St.		X		1935	Domestic Multiple	Duplex		Tudor Revival	Brick	84	481
323 W. Third St.		X		1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Red Brick	79	134
324 W. Third St.		X	03 : 11	1935	Domestic Single			Tudor Revival	Brick	79	133
400 W. Third St.		X		1935	Domestic Single			Tudor Revival	Red Brick	84	482
618 W. Tiernont St.		X	04 : 25	1945	Domestic Single			Colonial Revival	Brick	84	483
									Red Brick	94	888

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type		Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
		HSM	M	SL			Roll	Frame	Slide	Property Type				
619	W. Tremont St.	X			04 : 24	1950	Domestic Single			Colonial Revival	Red Brick	94	887	
630	W. Tremont St.		X			1950	Domestic Single			Colonial Revival	Mixed Brick	94	890	
631	W. Tremont St.		X			1950	Domestic Single			Monterey	Mixed Brick	94	889	
200 blk.	E. Troup Hwy.			X	05 : 11	1940	Infrastructure and Utilities	Water Tank			Steel	95	945A	
200 blk.	E. Troup Hwy.		X		05 : 12	1940	Infrastructure and Utilities	Pumphouse		Colonial Revival	Brick	95	945B	
412	E. Troup Hwy.			X		1955	Domestic Multiple	Duplex			Red Brick	98	978	
418	E. Troup Hwy.			X		1955	Domestic Multiple	Duplex			Red Brick	98	977	
426	E. Troup Hwy.			X		1955	Domestic Multiple	Duplex			Red Brick	98	979	
502	E. Troup Hwy.			X		1955	Domestic Single				Yellow Brick	98	976	
508	E. Troup Hwy.			X		1955	Domestic Single				Yellow Brick	98	975	
528	E. Troup Hwy.			X		1950	Domestic Single				Brick	98	974	
600 blk.	E. Troup Hwy.			X		1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Yellow Brick	97	1287A	
600 blk.	E. Troup Hwy.			X		1935	Domestic Auxiliary	Garage Apartment			Wood	97	1287B	
601	E. Troup Hwy.			X		1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Brick	97	1289	
612	E. Troup Hwy.			X		1945	Domestic Single			Colonial Revival	Yellow Brick	98	973	
613	E. Troup Hwy.			X		1935	Domestic Single	Cross Gabled Bungalow		Tudor Revival	Red Brick	97	1288	
626 -24	E. Troup Hwy.			X		1940	Domestic Multiple	Duplex		Tudor Revival	Red Brick	98	972	
628	E. Troup Hwy.			X		1935	Domestic Single			Tudor Revival	Mixed Brick	98	971	
700 blk.	E. Troup Hwy.			X	05 : 17	1935	Domestic Single	Cross Gabled Bungalow			Red Brick	97	1290	
800 blk.	E. Troup Hwy.			X	05 : 18	1930	Domestic Single			Classical Revival	Brick	97A	1354A	
800 blk.	E. Troup Hwy. (rear)			X		1930	Domestic Auxiliary	Garage Apartment				97A	1354B	
800 blk.	E. Troup Hwy.			X		1940	Domestic Single			Colonial Revival	Brick	97A	1355	
806	E. Troup Hwy.			X	05 : 13	1935	Domestic Single			Colonial Revival	Brick	98	970	
910	E. Troup Hwy.			X	05 : 14	1940	Domestic Single			Colonial Revival	Brick	99	1128	
1100	E. Troup Hwy.			X		1935	Domestic Single			Tudor Revival	Mixed Brick	99	1127	
1104	E. Troup Hwy.			X		1935	Domestic Single			Tudor Revival	Brick	99	1126	
1900 blk.	S. Vine Ave.			X		1945	Domestic Single				Wood	93A	791	
1900 blk.	S. Vine Ave.			X		1945	Domestic Single				Synthetic Sliding	93A	792	
1900 blk.	S. Vine Ave.			X		1945	Domestic Single				Wood	93A	793	
1900 blk.	S. Vine Ave.			X		1945	Domestic Single				Brick	80	336	
1114	S. Wall Ave.			X		1940	Domestic Single	Cross Gabled Bungalow		Colonial Revival	Brick	80	336	
1115	S. Wall Ave.			X		1940	Domestic Single	Cross Gabled Bungalow		Minimal	Red Brick	80	335	
1118	S. Wall Ave.			X		1940	Domestic Single				Red Brick	80	337	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference		Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Mcp No.	I.D. No.
		H	S	M	SL	Roll			Frame	Slide				
1119	S. Wall Ave.		X					Domestic Single	Cross Gabled Bungalow	Colonial Revival	Brick	80	334	
1122	S. Wall Ave.		X				1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	80	338	
1125	S. Wall Ave.		X				1950	Domestic Single	Side Gabled Bungalow	Colonial Revival	Brick	80	333	
1200	S. Wall Ave.		X				1940	Domestic Single	Cross Gabled Bungalow	Tudor Revival	Brick	80	339	
1201	S. Wall Ave.		X				1940	Domestic Single	Side Gabled Bungalow	Colonial Revival	Brick	80	332	
1204	S. Wall Ave.		X				1940	Domestic Single		Colonial Revival	Yellow Brick	80	340	
1205	S. Wall Ave.		X				1940	Domestic Single			Brick	80	331	
1208	S. Wall Ave.		X				1940	Domestic Single	Cross Gabled Bungalow		Brick	80	341	
1210	S. Wall Ave.		X				1940	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Yellow Brick	80	342	
1211	S. Wall Ave.		X				1940	Domestic Single		Colonial Revival	Brick	80	330	
1215	S. Wall Ave.		X				1940	Domestic Single		Tudor Revival	Yellow Brick	80	329	
1219	S. Wall Ave.			X			1950	Domestic Single			Red Brick	80	328	
1220	S. Wall Ave.		X				1940	Domestic Single		Minimal	Red Brick	80	343	
1302	S. Wall Ave.		X				1940	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Brick	80	344	
1306	S. Wall Ave.			X			1945	Domestic Single			Brick	80	345	
1307	S. Wall Ave.		X				1945	Domestic Single		Minimal	Yellow Brick	80	327	
1310	S. Wall Ave.			X			1945	Domestic Single			Brick	80	346	
1311	S. Wall Ave.		X				1950	Domestic Single		Ranch/Minimal	Red Brick	80	326	
1314	S. Wall Ave.		X				1945	Domestic Single		Minimal	Brick	80	347	
1317	S. Wall Ave.		X				1940	Domestic Single		Colonial Revival	Brick	80	325	
1320	S. Wall Ave.		X				1945	Domestic Single			Yellow Brick	80	348	
1321	S. Wall Ave.		X				1945	Domestic Single		Colonial Revival	Brick	80	324	
1322	S. Wall Ave.		X				1945	Domestic Single		Ranch	Brick	80	349	
1324	S. Wall Ave.		X				1940	Domestic Single		Colonial Revival	Brick	80	323	
1328	S. Wall Ave.		X				1945	Domestic Single		Colonial	Yellow Brick	80	350	
1329	S. Wall Ave.		X				1945	Domestic Single		Minimal	Red Brick	80	322	
1400	S. Wall Ave.		X				1940	Domestic Single		Tudor Revival	Brick	80	351	
1401	S. Wall Ave.		X				1940	Domestic Single		Minimal	Brick	80	321	
1405	S. Wall Ave.		X				1940	Domestic Single		Tudor Revival	Brick	80	320	
1406	S. Wall Ave.		X				1940	Domestic Single	Cross Gabled Bungalow	Colonial Revival	Brick	80	*351A	
1406	S. Wall Ave. (rear)		X				1940	Domestic Auxiliary	Garage Apartment		Wood	80	*351B	
1414	S. Wall Ave.		X				1940	Domestic Single		Colonial	Brick	80	352	

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Priority			Photo Reference	Date	Property Type	Identification		Stylistic Influence	Exterior Materials	Map No.	I.D. No.
	H	SM	M/SL				L	Roll				
1417 S. Wall Ave.	X				02:28	Domestic Single			Colonial Revival	Mixed Brick	80	319
1427 S. Wall Ave.		X				Domestic Single			Colonial Revival	Brick	80	318
1428 S. Wall Ave.			X			Domestic Single			Colonial Revival	Brick	80	353
1504 S. Wall Ave.			X			Domestic Single			Colonial Revival	Red Brick	80	354
1505 S. Wall Ave.			X			Domestic Single			Colonial Revival	Yellow Brick	80	317
1508 S. Wall Ave.		X			02:29	Domestic Single			Tudor Revival	Red Brick	80	355
1521 S. Wall Ave.			X			Domestic Single				Pink Brick	80	316
1522 S. Wall Ave.				X		Domestic Single			Colonial Revival	Stucco	80	356
1526 S. Wall Ave.			X			Domestic Single			Colonial Revival	Red Brick	80	357
1529 S. Wall Ave.		X			02:27	Domestic Single			Tudor Revival	Red Brick	80	315A
1529 S. Wall Ave. (rear)		X				Domestic Single			Side Gabled Bungalow	Wood	80	315B
1600 S. Wall Ave.			X			Domestic Single			Tudor Revival	Yellow Brick	80	358
1601 S. Wall Ave.			X			Domestic Single				Yellow Brick	80	314A
1601 S. Wall Ave. (rear)				X		Domestic Auxiliary			Garage Apartment	Wood	80	314B
1604 S. Wall Ave.		X				Domestic Single			Minimal	Yellow Brick	80	359
1605 S. Wall Ave.		X				Domestic Single			Minimal	Brick	80	313
1610 S. Wall Ave.		X				Domestic Single			Colonial Revival	Red Brick	80	360
1611 S. Wall Ave.		X				Domestic Single			Ranch	Brick	80	312
1900 blk. S. Wall Ave.		X				Domestic Single			Ranch	Red Brick	98	1003
1904 S. Wall Ave.		X				Domestic Single			Ranch	Wood	98	1004
1912 S. Wall Ave.		X				Domestic Single			Ranch	Mixed Brick	98	1005
1920 S. Wall Ave.		X				Domestic Single			Ranch	Red Brick	98	1006
1924 S. Wall Ave.			X			Domestic Single			Ranch	Yellow Brick	98	1007
2002 S. Wall Ave.			X			Domestic Single			Ranch	Yellow Brick	98	1008
2026 S. Wall Ave.			X			Domestic Single			Ranch	Yellow Brick	98	1009
2034 S. Wall Ave.			X			Domestic Single			Ranch	Wood	98	1010
2102 S. Wall Ave.			X			Domestic Single			Ranch	Red Brick	98	1011
2108 S. Wall Ave.			X			Domestic Single			Ranch	Red Brick	98	1012
1903 S. Willey Ave.		X				Domestic Single				Yellow Brick	98	1113
1905 S. Willey Ave.			X			Domestic Single				Red Brick	98	1112
1910 S. Willey Ave.			X			Domestic Single			Ranch	Red Brick	99	1141
1913 S. Willey Ave.			X			Domestic Single				Yellow Brick	98	1111

Tyler, Phase IV, South Historic Resources Inventory (By Address)

Diane E. Williams & Associates

Street Number and Name	Address	Priority			Photo Reference	Date	Property Type	Identification			Exterior Materials	Map No.	I.D. No.
		H	S	M				Subtype	Stylistic Influence				
1924	S. Wiley Ave.		X			1955	Domestic Single			Ranch	Red Brick	99	1140
1927	S. Wiley Ave.		X			1950	Domestic Single				Yellow Brick	98	1110
1931	S. Wiley Ave.		X			1950	Domestic Single				Red Brick	98	1109
1932	S. Wiley Ave.			X		1955	Domestic Single			Ranch	Red Brick	99	1139
1936	S. Wiley Ave.		X			1950	Domestic Single				Red Brick	99	1138
2002	S. Wiley Ave.		X			1945	Domestic Single			Minimal	Red Brick	99	1137
2003	S. Wiley Ave.		X			1950	Domestic Single				Yellow Brick	98	1108
2005	S. Wiley Ave.		X			1950	Domestic Single				Red Brick	98	1107
2007	S. Wiley Ave.		X			1940	Domestic Single			Tudor Revival	Yellow Brick	98	1106
2008	S. Wiley Ave.		X			1935	Domestic Single			Cross Gabled Bungalow	Wood	99	1136
2011	S. Wiley Ave.		X			1950	Domestic Single				Brick	98	1105
2018	S. Wiley Ave.			X		1955	Domestic Single				Red Brick	99	1135
2021	S. Wiley Ave.			X		1950	Domestic Single				Red Brick	98	1104
2023	S. Wiley Ave.		X			1950	Domestic Single				Red Brick	98	1103
2024	S. Wiley Ave.		X			1940	Domestic Single			Cross Gabled Bungalow	Yellow Brick	99	1134
2028	S. Wiley Ave.			X		1890	Domestic Single			Center Passage	Wood	99	1133
2100 blk.	S. Wiley Ave.			X		1950	Domestic Single				Red Brick/Synthetic	98	1098
2101	S. Wiley Ave.		X			1950	Domestic Single				Brick	98	1102
2102	S. Wiley Ave.		X			1940	Domestic Single				Red Brick/Wood	99	1132
2105	S. Wiley Ave.		X			1940	Domestic Single			Tudor Revival	Yellow Brick	98	1101
2106	S. Wiley Ave.		X			1945	Domestic Single				Red Brick	99	1131
2111	S. Wiley Ave.		X			1950	Domestic Single				Red Brick	98	1100
2112	S. Wiley Ave.		X			1940	Domestic Single			Colonial Revival	Asbestos	99	1130
2115	S. Wiley Ave.		X			1945	Domestic Single				Yellow Brick	98	1099
400 blk.	E. Wilma St.		X			1940	Domestic Single			Colonial Revival	Wood	103	1358
600 blk.	E. Wilma St.		X			1950	Domestic Single				Wood	103	1359
624	E. Wilma St.		X			1945	Domestic Single				Wood	103	1360
630	E. Wilma St.			X		1945	Domestic Single				Wood	103	1361
634	E. Wilma St.		X			1945	Domestic Single				Asbestos	103	1362
640	E. Wilma St.			X		1945	Domestic Single				Vinyl Siding	103	1363
648	E. Wilma St.		X			1945	Domestic Single				Vinyl Siding	103	1364